

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090519/APA3Q2(N)
Date: 07/02/2025**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002571
Claimant Vehicle No :	SMH6340H	Insured Vehicle No :	SLK9278G
Date of Loss:	27/09/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0011512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH6340H	Engine No:	G4FGJU076284
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Chassis No:	KMHD841CMKU846883
Reg. Date:	29/01/2019 (Man. Year: 2018)	Odometer:	186249 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,012.80	5,229.20	2,783.60	34.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,240.00	1,140.00	47.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,392.80	6,469.20	3,923.60	37.75
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	10,392.80	5,100.00	5,292.80	50.93
+ GST 9.00/9.00% (S\$)	935.35	459.00	476.35	50.93
Nett Amount (S\$)	11,328.15	5,559.00	5,769.15	50.93
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,086.25		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment:	30/09/2024	N-51 Automotive Pte Ltd (HQ)
Date Inspected:	30/09/2024 Inspected At:	BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2024)
Parts: 143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH6340H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	573.00 FL	*573.00 FL
2	1		*FRONT BUMPER LH FOGLAMP	Cracked	185.00 FL	*185.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	717.00 FL	*- FL
4	1		*FRONT BUMPER SIDE AIR DUCT GARNISH LH	Cracked	65.00 FL	*65.00 FL
5	1		*FRONT BUMPER SIDE AIR DUCT LH	Deformed	125.00 FL	*125.00 FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	40.00 FL	*40.00 FL
7	1		*FRONT GRILLE	Not Necessary	1,215.00 FL	*- FL
8	1		*FRONT LH FENDER	Dented	1,227.00 FL	*1,227.00 FL
9	1		*FRONT LH FENDER INNER SHIELD	Torn	105.00 FL	*105.00 FL
10	1		*FRONT LH HEADLAMP	Cut	3,354.00 FL	*3,354.00 FL
11	1		*FRONT LH HEADLAMP LOWER BRACKET	Not Necessary	35.00 FL	*- FL
12	1		*FRONT LH KNUCKLE ARM	Not Necessary	390.00 FL	*- FL
13	1		*FRONT LH KNUCKLE ARM BEARING	Not Necessary	452.00 FL	*- FL
14	1		*FRONT LH SPORT RIM	Cut	746.40 FS	*450.00 FS
15	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*FRONT LH TYRE	Cut	380.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,709.40	6,364.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,696.60	1,134.80
Total Parts (\$\$)	8,012.80	5,229.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	120.00	0.00
3	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
6	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	30.00
Gross Labour Cost (\$\$)			2,380.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >