10/10/24, 2:39 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090520/TVP3M4

Date: 10/10/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MV004733 **Claimant Vehicle** SHD4594K Insured Vehicle No: SKT8768E

No:

Date of Loss: 29/09/2024 Nature of Claim: TP Claim No: M2405644

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD4594K

TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Make & Model: Engine No: 2ZR2G33277

Reg. Date: 27/12/2019 (Man. Year: 2019) Chassis No: JTDKB3FU403090718

Colour: Blue Odometer: 551261 km

Engine Capacity: 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Footbrake (Serviceable): Yes Pre-accident Condition: Yes **Engine Modification:** Good Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,450.03	1,775.92	5,674.11	76.16
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,940.00	1,350.00	590.00	30.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,402.03	3,137.92	6,264.11	66.63
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	9,402.03	2,500.00	6,902.03	73.41
+ GST 9.00/9.00% (S\$)	846.18	225.00	621.18	73.41
Nett Amount (S\$)	10,248.21	2,725.00	7,523.21	73.41

INSPECTION

Date Inspected:

Date of Assignment: 30/09/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

COMFORTDELGRO ENGINEERING PTE LTD

(LOYANG) 01/10/2024 Inspected At:

59 LOYANG DRIVE SINGAPORE 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/10/24, 2:39 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2024)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD4594K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No	. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	503.04 FL	*503.04 FL
2	1	*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1	*REAR BUMPER LOWER COVER	Deformed	654.96 FL	*654.96 FL
4	1	*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
5	1	*REAR BUMPER SIDE RETAINER LH	Not Necessary	94.80 FL	*- FL
6	1	*REAR BUMPER REFLECTOR LH	Not Necessary	55.00 FL	*- FL
7	1	*FRONT BUMPER COVER	Deformed	499.90 FL	*499.90 FL
8	1	*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1	*HEADLAMP LH	Not Necessary	2,735.28 FL	*- FL
10	1	*HEADLAMP RH	Not Necessary	2,735.28 FL	*- FL
11	1	*FRT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	*- FL
12	1	*FRT BUMPER SPONGE	Not Necessary	78.80 FL	*- FL
13	1	*FRT BUMPER LOWER GRILLE	Not Necessary	166.90 FL	*- FL
14	1	*FRT BUMPER RADIATOR GRILLE	Cracked	438.00 FL	*438.00 FL
15	1	*FRT BUMPER GRILLE GARNISH	Not Necessary	186.90 FL	*- FL
16	1	*RADIATOR GRILLE EMBLEM	Cracked	88.00 FL	*88.00 FL
17	1	*FRONT BUMPER EXTENSION PLATE	Not Necessary	99.00 FL	*- FL
18	1	*FRT BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
19	1	*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F
20	1	*REAR REVERSE SENSOR	Not Necessary	180.00 F	*- F
21	1	*FRT NUMBER PLATE WITH TRIM COVER	Cut	55.00 F	*55.00 F
F=Fra	anchise part. L=Lis	tltemDisc.	_		
			Sub Total (S\$)	9,838.38	2,332.90
		- List Item Discount on	L Items 25.00/25.00% (S\$)	2,388.35	556.98
			Total Parts (S\$)	7,450.03	1,775.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			,
1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
PANEL BEATING	New	1,200.00	760.00
SPRAY PAINTING CHARGE	New	600.00	560.00
REMOVE & REFIX REVERSE SENSOR	New	80.00	30.00
CHECK LIGHTING	New	60.00	0.00
	Gross Labour Cost (S\$)	1,940.00	1,350.00
	our Items PANEL BEATING SPRAY PAINTING CHARGE REMOVE & REFIX REVERSE SENSOR	PANEL BEATING New SPRAY PAINTING CHARGE New REMOVE & REFIX REVERSE SENSOR New CHECK LIGHTING New	DUIT Items PANEL BEATING New 1,200.00 SPRAY PAINTING CHARGE New 600.00 REMOVE & REFIX REVERSE SENSOR New 80.00 CHECK LIGHTING New 60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >