

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24090521/UVP3E2
Date: 14/10/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002240609
Claimant Vehicle No :	SJW7879X	Insured Vehicle No :	SCF8007L
Date of Loss:	27/09/2024	Nature of Claim:	TP
		Claim No:	375026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW7879X		
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI 5G13GZ W/O	Engine No:	CXS258826
Reg. Date:	30/09/2015 (Man. Year: 2015)	Chassis No:	WVWZZZAUZFW356497
Colour:	White	Odometer:	97875 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,313.58	4,161.89	11,151.69	72.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,170.00	1,950.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,433.58	5,331.89	13,101.69	71.08
Approved Total (Overridden) (\$\$)		4,200.00		
Nett Amount (\$\$)	18,433.58	4,200.00	14,233.58	77.22

INSPECTION

Date of Assignment:	30/09/2024	
Date Inspected:	30/09/2024	Inspected At: Galaxy Autocare Pte Ltd (HQ) 13 Kaki Bukit Road 4 #01-23 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	144	VOLKSWAGEN GOLF 1.4 A7 TSI 5G13GZ W/O HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW7879X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	2,250.00 FL	*1,076.45 FL
2	1		*FRONT BUMPER RETAINER LH	Cracked	175.00 FL	*66.00 FL
3	1		*FRONT BUMPER RETAINER RH	Not Necessary	175.00 FL	*- FL
4	1		*FRONT BUMPER CENTER GRILLE	Not Necessary	758.20 FL	*- FL
5	1		*FRONT SHOCK ABSORBER LH	Not Necessary	785.00 FL	*- FL
6	1		*FRONT ABSORBER MOUNTING LH	Not Necessary	250.00 FL	*- FL
7	1		*FRONT ABSORBER STOPPER LH	Not Necessary	80.00 FL	*- FL
8	1		*FRONT LOWER ARM LH	Not Necessary	756.00 FL	*- FL
9	1		*FRONT KNUCKLE LH	Serviceable	655.00 FL	*- FL
10	1		*FRONT WHEEL BEARING LH	Damaged	388.00 FL	*388.00 FL
11	1		*FRONT SHOCK ABSORBER RH	Serviceable	785.00 FL	*- FL
12	1		*FRONT ABSORBER MOUNTING	Not Necessary	250.00 FL	*- FL
13	1		*FRONT ABSORBER STOPPER	Not Necessary	80.00 FL	*- FL
14	1		*FRONT LOWER ARM RH	Serviceable	756.00 FL	*- FL
15	1		*FRONT KNUCKLE RH	Serviceable	655.00 FL	*- FL
16	1		*FRONT WHEEL BEARING RH	Damaged	388.00 FL	*388.00 FL
17	1		*STABILIZER BAR LINK RH	Not Necessary	208.00 FL	*- FL
18	1		*FRONT FENDER LH	Distorted	985.00 FL	*547.75 FL
19	1		*FRONT FENDER INNER SHIELD LH	Torn	425.00 FL	*157.40 FL
20	1		*FRONT HEADLAMP BAKER LH	Not Necessary	289.00 FL	*- FL
21	1		*FRONT HEADLAMP LH	Cracked	2,245.00 FL	*980.50 FL
22	1		*SET FRONT NUMBER PLATE	Not Necessary	90.00 FS	*- FS
23	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*SET FRONT GRILLE CLIP	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT FENDER CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET FRONT PARKING SENSOR	Not Necessary	480.00 FS	*- FS
27	1		*SET TYRES	Not Necessary	500.00 FS	*- FS
28	1		*SET RIM LH & RH	Bent / Warped	1,200.00 FS	*800.00 FS
29	1		*FRONT BUMPER GRILLE LH	Scratched	988.00 FL	*98.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,746.20	4,532.10
- List Item Discount on L Items 10.00/10.00% (S\$)	1,432.62	370.21
Total Parts (S\$)	15,313.58	4,161.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	New	200.00	20.00
2	REMOVE, REFIT FRONT LINING, TRIM AND GARNISH	New	300.00	0.00
3	REMOVE AND RENEW FRONT REVERSE SENSOR	New	150.00	0.00
4	PANEL BEATING ON FRONT AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,000.00	400.00
5	SPRAY PAINTING ON FRONT AFFECTED AREAS	New	1,000.00	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	350.00	30.00
7	TO R&R FRONT UNDERCARRIAGE	New	120.00	120.00
Gross Labour Cost (\$)			3,120.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >