

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090523/DUA3Q2
Date: 13/03/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0007412
Claimant Vehicle No :	SHC7007A	Insured Vehicle No :	SLQ3161S
Date of Loss:	27/09/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0011404

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7007A		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (AUTO) (2WD) (A)	Engine No:	2ZR2P82944
Reg. Date:	28/04/2022 (Man. Year: 2022)	Chassis No:	JTDKB3FU803096442
Colour:	Yellow	Odometer:	290618 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,351.86	8,443.13	19,908.73	70.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,420.00	3,080.00	68.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,851.86	9,863.13	22,988.73	69.98
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	32,851.86	7,900.00	24,951.86	75.95
+ GST 9.00/9.00% (S\$)	2,956.67	711.00	2,245.67	75.95
Nett Amount (S\$)	35,808.53	8,611.00	27,197.53	75.95
+ Car Rental (10.0 x S\$119.68/day) (S\$)		1,196.80		
+ Loss of Earnings (10.0 x S\$40.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		10,315.05		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment:	01/10/2024		
Date Inspected:	01/10/2024	Inspected At:	BIFROST AUTO PTE LTD - LOYANG (HQ) 59 Loyang Drive Level 4 Room 7 Singapore 508969
Estimated Period of Repair:	7.0 days		

Adjuster: BRYAN TANI

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2025)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (AUTO)(2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7007A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Bent	1,577.24 FL	*1,577.24 FL
2	1		*REAR TRUNK LID LOCK	Damaged	641.06 FL	*641.06 FL
3	1		*REAR TRUNK LID LOCK COVER	Not Necessary	129.80 FL	*- FL
4	1		*REAR TRUNK LID LOCK SWITCH	Not Necessary	468.90 FL	*- FL
5	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	303.10 FL	*- FL
6	1		*REAR TRUNK LID RUBBER	Necessary	511.28 FL	*362.50 FL
7	1		*REAR TRUNK LID LAMP G5 (N/S)	Broken	891.52 FL	*891.52 FL
8	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Not Necessary	2,197.58 FL	*- FL
9	1		*BOARD ASSY ,BACK DOOR TRIM	Not Necessary	356.16 FL	*- FL
10	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Broken	1,845.58 FL	*913.60 FL
11	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	85.12 FL	*85.12 FL
12	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	73.36 FL	*73.36 FL
13	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	74.06 FL	*74.06 FL
14	1		*THIRD BRAKE LIGHT	Not Necessary	552.58 FL	*- FL
15	1		*REAR TRUNK LID STRIKER	Not Necessary	138.18 FL	*- FL
16	2		*REAR TRUNK LID HINGE (LH/RH)	Not Necessary	530.60 FL	*- FL
17	2		*REAR TRUNK LID ABSORBER (LH/RH)	Not Necessary	805.00 FL	*- FL
18	2		*REAR TRUNK LID ABSORBER BRACKET (LH/RH)	Not Necessary	358.12 FL	*- FL
19	2		*REAR TRUNK LID STOPPER (LH/RH)	Not Necessary	237.44 FL	*- FL
20	1		*SPOILERSUB-ASSY ,REAR	Not Necessary	1,335.18 FL	*- FL
21	1		*REAR BUMPER	Dented	642.04 FL	*642.04 FL
22	1		*REAR BUMPER REINFORCEMENT	Dented	446.32 FL	*446.32 FL
23	1		*REAR BUMPER UNDER COVER	Not Necessary	773.64 FL	*- FL
24	2		*REAR BUMPER SISDE RETAINER	Not Necessary	315.56 FL	*- FL
25	1		*REAR BUMPER UNDER CENTRE COVER	Dislodged	773.64 FL	*773.64 FL
26	1		*REAR BUMPER TOWING COVER	Not Necessary	115.78 FL	*- FL
27	1		*REAR BUMPER CLIPS	Necessary	30.80 FL	*30.80 FL
28	2		*REAR BUMPER SIDE CLIP	Not Necessary	70.00 FL	*- FL
29	2		*REAR BUMPER UPPER STOPPER	Not Necessary	213.92 FL	*- FL
30	1		*ARM SUB-ASSY ,REAR BUMPER RH	Not Necessary	195.44 FL	*- FL
31	1		*REAR BUMPER UNDER SIDE COVER (RH)	Not Necessary	324.80 FL	*- FL
32	1		*RETAINER ,REAR BUMPER ,SIDE RH	Not Necessary	132.72 FL	*- FL
33	2		*RETAINER ,REAR BUMPER UPPER SIDE (LH/RH)	Not Necessary	85.96 FL	*- FL
34	1		*RETAINER ,REAR BUMPER SIDE LH	Not Necessary	132.72 FL	*- FL
35	1		*REAR BUMPER UNDER SIDE COVER (LH)	Broken	324.80 FL	*324.80 FL
36	1		*ARM SUB-ASSY ,REAR BUMPER LH	Not Necessary	195.44 FL	*- FL
37	1		*REAR BUMPER LOWER COVER GARNISH G5	Dented	963.63 FL	*963.63 FL
38	1		*TAIL LAMP ASSY (UPPER) G5	N/S Broken / O/S Not Necessary	1,885.80 FL	*942.90 FL
39	2		*TAIL LAMP ASSY (LOWER) G5	Not Necessary	1,721.16 FL	*- FL
40	2		*TAIL LAMP QUARTER PANEL	Repair	604.80 FL	*- FL
41	1		*REAR END PANEL GARNISH COVER	Serviceable	138.90 FL	*- FL
42	2		*TAIL LAMP SIDE COVER	Not Necessary	716.80 FL	*- FL
43	1		*LAMP ASSY ,SIDE TURN SIGNAL RH	Not Necessary	91.42 FL	*- FL
44	1		*LAMP ASSY ,SIDE TURN SIGNAL LH	Not Necessary	91.42 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR END PANEL	Dented	842.94 FL	*842.94 FL
46	1		*REAR END PANEL GARNISH	Serviceable	294.80 FL	*- FL
47	1		*REAR SPARE TYRE PANEL	Not Necessary	960.80 FL	*- FL
48	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Bent	668.90 FL	*668.90 FL
49	1		*REAR FIBER TOOL BOX TRIM	Not Necessary	557.20 FL	*- FL
50	1		*SPARE TYRE LOCK NUT	Not Necessary	123.76 FL	*- FL
51	1		*REAR EXHAUST PIPE RH	Not Necessary	1,628.76 FL	*- FL
52	1		*REAR EXHAUST PIPE INSULATOR	Bent	440.44 FL	*440.44 FL
53	2		*REAR FENDER SHIELD (LH/RH)	Not Necessary	375.76 FL	*- FL
54	2		*REAR FENDER TRIMBOARD (LH/RH)	Not Necessary	2,030.00 FL	*- FL
55	1		*REAR WINDSCREEN GLASS W/MOULDING	Not Necessary	2,489.62 FL	*- FL
56	1		*REAR TRUNK LOWER W/S MOULDING	Not Necessary	180.00 FS	*- FS
57	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
58	1		*REAR NO PLATE WITH TRIM COVER	Not Necessary	140.00 FS	*- FS
59	1		*REAR TRUNK LID APPS STICKER	Necessary	56.00 FS	*56.00 FS
60	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	84.00 FS	*84.00 FS
61	1		*REAR BUMPER REVERSE SENSOR	Damaged	189.98 FS	*189.98 FS
62	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	35,254.33	11,116.85
- List Item Discount on L Items 20.00/25.00% (\$)	6,902.47	2,673.72
Total Parts (\$)	28,351.86	8,443.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING CHARGE	New	1,400.00	600.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REPAIR EXHAUST PIPE	New	80.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,500.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >