



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLK 6347K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HEADLAMP LH	NOT NECESSARY	\$1,875.00	\$0.00
1	HEAD LAMP UPPER BRACKET LH	NOT NECESSARY	\$89.00	\$0.00
1	HEADLAMP LOWER BRACKET LH	NOT NECESSARY	\$55.00	\$0.00
1	FRONT BUMPER	DEFORMED	\$798.00	\$762.20
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	\$68.00	\$0.00
1	FRONT BUMPER LOWER	DEFORMED	\$589.00	\$420.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$312.00	\$0.00
1	FRONT FENDER LH	BENT	\$830.00	\$586.00
1	FRONT FENDER 'HYBRID' EMBLEM	NECESSARY	\$86.00	\$86.00
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	\$228.60	\$0.00
1	FRONT WHEEL ARCH GARNISH LH	DEFORMED	\$298.20	\$248.50
	<b>LESS 20.00% DISCOUNT</b>		(\$1,045.76)	(\$420.54)
			\$4,183.04	\$1,682.16

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET RADIATOR GRILLE CLIPS (SN)	NOT NECESSARY	\$40.00	\$0.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	SET FRONT FENDER INNER LINER CLIPS (SN)	NECESSARY	\$40.00	\$30.00
1	SET FRONT WHEEL ARCH GARNISH CLIPS (SN)	NECESSARY	\$40.00	\$30.00
1	FRONT WHEEL RIM (SN)	SCRATCHED	\$150.00	\$150.00
			\$320.00	\$240.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS		\$800.00	\$500.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND AFFECTED AREA		\$800.00	\$400.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS		\$80.00	\$40.00
	WHEEL ALIGNMENT		\$80.00	\$60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS		\$80.00	\$40.00
			\$1,840.00	\$1,040.00
GRAND TOTAL			\$6,343.04	\$2,962.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,350.00
Report Ref No: CS/AGI24090524/Rqp3e2				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.