



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. NCS 1642

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY	TO REPAIR SEE LABOUR	960.00	-
1	FORK UNDER BRACKET	SERVICEABLE	260.00	-
1	FRONT RIM	NOT NECESSARY	480.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	285.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	88.00	-
1	FRONT RIM BEARING	NOT NECESSARY	90.00	-
1	HANDLE BAR	BENT	255.00	150.00
1	HANDLE BAR END	NOT FITTED	88.00	-
1	SET HAND GRIP	TORN	76.00	60.00
1	METER ASSY	NOT NECESSARY	455.00	-
1	METER COVER	CRACKED	135.00	135.00
1	HEADLAMP ASSY	BROKEN	485.00	485.00
1	BRAKE LEVER	BENT	95.00	60.00
1	FRONT SIGNALS	CRACKED	185.00	90.00
1	SET SIDE MIRROR	DAMAGED	128.00	80.00
1	SET FAIRING ASSY	CRACKED	735.00	600.00
1	FRONT FOOTREST BRACKET	BENT	225.00	150.00
1	FRONT FOOTREST RUBBER	TORN	95.00	60.00
1	BASKET	SERVICEABLE	125.00	-
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	165.00	-
1	EXHAUST ASSY	CUT/DAMAGED	680.00	680.00
1	EXHAUST PROTECTOR	BENT	165.00	110.00
1	REAR HANDLE	CUT	280.00	150.00
1	SET REAR FOOTREST	SERVICEABLE	125.00	-
1	SET REAR FOOTREST BRACKET	NOT NECESSARY	325.00	-
	LESS 10% DISCOUNT		-698.50	-281.00
			6,286.50	2,529.00
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NECESSARY/BENT	38.00	30.00

Report Ref No. CS/FCI24100001/Unp3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	96.00	-
1	STICKER (SN)	NECESSARY	120.00	60.00
			340.00	90.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	420.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK TUBE ASSY AND BRAKE PEDAL.		450.00	300.00
			950.00	300.00
GRAND TOTAL			7,576.50	2,919.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)				1,000.00

Report Ref No. CS/FCI24100001/Unp3m4(N)

MARKET VALUE: RM3,3000 (EST)-LTA REIMBURSEMENT VALUE: RM0.00=NETT VALUE: RM3,300

WORKSHOP DID NOT ARRANGE AFTER REPAIR PHOTOS.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.