

## CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

CITROËN

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792

### **ESTIMATE**

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Invoice Name & Address			Owner Name & Vehicle Info					
	Yue Zheng			Cust No/Name /YUE ZHENG				
	ruc zneng			Reg No/Reg Date	SLN4224D	/ 03/05/201	.7	
		DMIRALTY DR		Date In/Mileage	/	0		
	#12-286 SINGAPORE	750252		Chassis No	VF73ABHZTGJ8	79640		
	SINGAPORE	752555		Engine No	10JBHD306927	7		
	Contact No	Mobile: 96189253		Make/Model	CIT/GC4P 1.6		AT6 INTEN	SIVE MI
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Colour/Trim	WPP BLANC BA			
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	·····	
CSM00077	Cash	30/09/2024/ 18:42	TLL	1210/ Lim Teng K	eat	10473	····	
		Description of Good	·		Qty	Unit Price	Disc%	Amount
	AIR DAYS O							2160.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRY	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG	MPER, FRT LHS FENDER, FFECTED AREA  BUMPER, FRT LHS FEND  TON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM	ROL SYSTEM		1730 00	0.00	2160.00 1650.00 160.00 200.00 480.00 80.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00	1739.00 457.00	0.00	1650.00 160.00 160.00 200.00 480.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M BUMPER	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BRACKET MOULDING	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00	457.00 251.00	0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M BUMPER	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BUMPER BRACKET MOULDING	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00	457.00 251.00 380.00	0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRY SUNDRY M FRONT M BUMPER M BUMPER M BUMPER	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER E BRACKET MOULDING UBBR BOOT	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00 1.00	457.00 251.00 380.00 373.00	0.00 0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M BUMPER M BUMPER M BMPR R	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BRACKET MOULDING WOULDING UBBR BOOT GRILLE INFE	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00	457.00 251.00 380.00	0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00 519.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BRACKET MOULDING WOULDING UBBR BOOT GRILLE INFE	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00 1.00 1.00	457.00 251.00 380.00 373.00 519.00	0.00 0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BRACKET MOULDING MOULDING UBBR BOOT GRILLE INFE T SET T SET LAT	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	457.00 251.00 380.00 373.00 519.00 181.00 181.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00 519.00 181.00 181.00 137.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M BRACKE M ABSORE M BUMPER	O LACE FRT BL ACCIDENT A O WORK ON FRT UST PROOFIN BODY SEALAN 9 CK WIRING 8 1 RY OUT DIAG ES BUMPER BRACKET MOULDING MOULDING UBBR BOOT GRILLE INFE T SET T SET LAT ERS SET	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	457.00 251.00 380.00 373.00 519.00 181.00 187.00 735.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00 519.00 181.00 181.00 137.00 735.00
OO REP E PNT8800 TO REP REPAIR E PNT9800 PAINT M SUNDRY ANTI-R M SUNDRY APPLY A 5490009 TO CHE A 1002890 TO CAR M SUNDRY SUNDRI M FRONT M BUMPER M BRACKE M ABSORE M BUMPER	O LACE FRT BU ACCIDENT AO WORK ON FRI UST PROOFIN BODY SEALAN 9 CK WIRING & 1 RY OUT DIAGE BUMPER BRACKET MOULDING BUBBR BOOT GRILLE INFERT SET LATHERS SET BRACKET	FFECTED AREA BUMPER, FRT LHS FEND G IT ON AFFECTED AREA CHASSIS ELECTRICAL S	ER YSTEM		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	457.00 251.00 380.00 373.00 519.00 181.00 181.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	1650.00 160.00 160.00 200.00 480.00 80.00 1739.00 457.00 251.00 380.00 373.00 519.00 181.00 181.00 137.00

Authorized signatory and company stamp

Confirm & accepted by

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur,

required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

CITROËN

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792

### **ESTIMATE**

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info				
	Vuo 7hong		Cust No/Name	/YUI	ZHENG			
Yue Zheng				Reg No/Reg Date	SLN4224D	/ 03/05/201	.7	
	BLK 353B ADMIRALTY DR #12-286 SINGAPORE 752353			Date In/Mileage	/ 0 VF73ABHZTGJ879640 10JBHD3069277			
				Chassis No				
				Engine No				
	Contact No	Mobile: 96189253		Make/Model	CIT/GC4P 1.	6 BLUEHDI E <i>l</i>	T6 INTEN	SIVE ML
				Colour/Trim	WPP BLANC B	ANQUISE / I)	(F YATAGO	GREY
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00077	Cash	30/09/2024/ 18:42	TLL	1210/ Lim Teng	Keat	10473		
		Description of Goods	s / Services		Qty	Unit Price	Disc%	Amount
M FRONT	WING LH ASS				1.00	731.00	0.00	731.00
M ACCOUS	TIC SEAL				1.00	76.00	0.00	76.00
M FRONT	_IGHT LH				1.00	645.00	0.00	645.00

# Estimate

Co. Co. O constability		
Confirm & accepted by	Parts	6,933.00
	Labour	4,490.00
	Standard Menu	0.00
	Specialist Job	0.00
	Diagnostics Job	0.00
Authorized signatory and company atoms	Sundry/Others	400.00
Authorized signatory and company stamp	Total (w/o GST)	11,823.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.