



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SNP9088M MERCEDES CLA180

No	Qty	Parts Description	Estimated Parts Price
1	1	Door skirt base <i>Ren</i>	\$ 800.00 +
2	1	Rear fender <i>Ren</i>	\$ 1,500.00 +
3	1	Sensor-right <i>Ren</i>	\$ 300.00 +
4	1	Rear fender-right <i>Ren</i>	\$ 969.00 +
5	1	Sport rim <i>Ren</i>	\$ 1,200.00 <i>1000(SN). 500</i>
6	1	Door handle with sensor assy full set <i>Ren</i>	\$ 780.00 +
7	1	Rim cover <i>Ren</i>	\$ 90.00 +
8	1	wheel bearing-rear right side <i>Ren</i> <i>wheel alignment report</i>	\$ 850.00 550
9	1	Rear right side brake caliper <i>Ren</i>	\$ 250.00 +
10	1	Wheel hub <i>Ren</i>	\$ 980.00 +
11	1	Rear right side have handbrake sensor <i>Ren</i>	\$ 580.00 +
Parts Sub-total			\$ 8,299.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SNP9088M MERCEDES CLA180

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	12	Rear bumper clips	\$ 120.00 +
2	10	Rear bumper lower lip clips	\$ 100.00 +
3	6	Rear fender light clips	\$ 60.00 +
4	20	Rear right door clips <i>Ren</i>	\$ 100.00 +
5	20	Rear lower skirt clips	\$ 100.00 +
6	1	Rear number plate and casing	\$ 120.00 +
7	20	wheel arch mud guard clips	\$ 120.00 +
Special Nett Items Total			\$ 720.00



Xin Yun Auto Private Limited
辛运汽车服务有限公司
Tel: 6634 0858 Email: xinyunauto1@gmail.com
Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNP9088M
Modle: MERCEDES CLA180

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 x
2	Carry up body cavity preservation for affected area \$50 per panel x	\$ 150.00 30 x
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 800.00 200 ✓
4	Spray painting for accident affected damaged area, including: rear bumper, rear side fender, touch up door and lower skirt area <small>pls provide clera photos of the rar bumper</small>	\$ 1,000.00 400 200 rear fender only
5	Carry out wheel alignment -necessary accident from rear right side hit	\$ 120.00 80 report
6	Removing and installing rear fender compartment garnish, triming etc, to facilitate the necessary repair.	\$ 100.00 +
7	Rear wheel balancing	\$ 80.00 +
8	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00 x
9	Removing and installing rear fender internal garnish and triming to facilitate the necessary repair	\$ 120.00 +
10	Removing and install rear rim, wheel bearing and axel area parts	\$ 150.00 x
11	Carry out diagnosis check including cleaning accident fault code	\$ 150.00 +
12	Coding or programming	\$ 250.00 +
Total labour :		\$ 3,150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adm L
1/s 28/10/24.