

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLG 1157X					
	REPLACEMENT OF PARTS Scription of Parts Condition Workshop Estimate (\$) O AR FENDER LH TO REPAIR SEE LABOUR NOT NECESSARY \$198.00 AR FENDER WHEEL ARCH GARNISH LH SCRATCHED \$180.00 AR BUMPER LH TO REPAIR SEE LABOUR \$482.00					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR FENDER LH	TO REPAIR SEE LABOUR	\$752.00	\$0.00		
1	REAR FENDER INNER LINER LH	NOT NECESSARY	\$198.00	\$0.00		
1	REAR FENDER WHEEL ARCH GARNISH LH	SCRATCHED	\$180.00	\$168.00		
1	REAR BUMPER LH	TO REPAIR SEE LABOUR	\$482.00	\$0.00		
1	REAR BUMPER CENTRE	TO REPAIR SEE LABOUR	\$1,128.00	\$0.00		
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	\$72.00	\$0.00		
	LESS 20.00% DISCOUNT		(\$562.40)	(\$33.60)		
			\$2,249.60	\$134.40		
	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR FENDER INNER LINNER CLIP (SN)	NOT NECESSARY	\$80.00	\$0.00		
1	REAR WHEEL ARCH GARNISH CLIPS (SN)	NECESSARY	\$80.00	\$30.00		
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$60.00	\$0.00		
			\$220.00	\$30.00		
	Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS.		#000.00	0.400.00		

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (
TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH, REAR BUMPER LH AND REAR BUMPER CENTRE		\$800.00	\$400.0		
TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED		\$800.00	\$400.0		
TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	NOT NECESSARY	\$80.00	\$0.0		
TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	NOT NECESSARY	\$60.00	\$0.0		
		\$1,740.00	\$800.0		
GRAND TOTAL	\$4,209.60	\$964.4			
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$750.00		
Report Ref No: CS/AGI24100016/Rqp3m4					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.