



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHF 612H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER, REAR BUMPER	BUCKLED	\$612.68	\$612.68
1	COVER, REAR BUMPER, LOWER	SERVICEABLE	\$27.93	\$0.00
1	GUARD, REAR BUMPER, CENTER	CRACKED	\$472.19	\$472.19
1	RETAINER, REAR BUMPER SIDE, LH	SERVICEABLE	\$167.48	\$0.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	\$167.48	\$0.00
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	TO REPAIR SEE LABOUR	\$419.90	\$0.00
1	REFLECTOR ASSY, REFLEX, LH	SERVICEABLE	\$49.25	\$0.00
1	REFLECTOR ASSY, REFLEX, RH	SERVICEABLE	\$49.25	\$0.00
1	COVER, FLOOR UNDER, RH	SERVICEABLE	\$220.50	\$0.00
1	COVER, FLOOR UNDER, LH	SERVICEABLE	\$304.92	\$0.00
1	COVER, REAR FLOOR	SERVICEABLE	\$290.43	\$0.00
1	COVER, DECK TRIM, REAR	SERVICEABLE	\$159.39	\$0.00
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	\$824.46	\$0.00
	LESS 25.00% DISCOUNT		(\$941.47)	(\$271.22)
			\$2,824.39	\$813.65

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET PARKING AID (SN)	SERVICEABLE	\$700.00	\$0.00
1	REAR BUMPER CLIP (SN)	NECESSARY	\$65.00	\$60.00
1	END PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	REAR BUMPER PROTECTOR (SN)	NO SUCH PARTS	\$180.00	\$0.00
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$150.00	\$0.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	\$200.00	\$0.00
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	\$130.00	\$0.00
			\$1,485.00	\$60.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS	NOT NECESSARY	\$600.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,200.00	\$220.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, REAR BUMPER AND PANEL SUB-ASSY, BODY LOWER BACK		\$2,000.00	\$200.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	NOT NECESSARY	\$170.00	\$0.00
	TO TRANSFER OF TAILGATE FITTINGS AND CONDUCT WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
	TO REINSTALL REAR BUMPER PARKING SENSOR		\$170.00	\$50.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	NOT NECESSARY	\$220.00	\$0.00
			\$5,250.00	\$470.00
GRAND TOTAL			\$9,559.39	\$1,343.65
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,050.00
Report Ref No: CS/FCI24100020/Knp3m4				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.