



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100021/Knp3e2
16 RAFFLES QUAY	Date:	22/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1542X	Veh. Inspected	SGY 4673S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008620MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	01/10/2024

2. Vehicle Details

Make & Model	TOYOTA ALTIS (A)	C.C	1598
Engine No.	3ZZ4691850	Year of Reg.	27/09/2007
Chassis No.	MR053ZEC107154129	Colour	METALLIC GREY
Odometer	156127 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/60R15	NEXEN	6
L/H Front Tyre	195/60R15	NEXEN	6
R/H Rear Tyre	195/60R15	NEXEN	8
L/H Rear Tyre	195/60R15	NEXEN	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/09/2024	Inspection Date	14/10/2024
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days