10/18/24, 10:04 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III24100022/TNP3M4

Date: 18/10/2024

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000131\_04

**Claimant Vehicle** SNP9291S Insured Vehicle No: GBC7258M

No:

Date of Loss: 29/09/2024 Nature of Claim: ΤP Claim No: MFL2024D0011800

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SNP9291S** Reg No:

Make & Model: TOYOTA SIENTA, 1.5 HYBRID (A) Engine No: M15AY934614

Reg. Date: 21/03/2024 (Man. Year: 2024) Chassis No: JTDBBBA350L001487

Colour: Odometer: 10697 km Beige

**Engine Capacity:** 1490 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

**CONDITION OF TYRES** 

Front Tyre Size: 175/70R14 175/70R14 Rear Tyre Size: Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repa	airer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Nett Amount (S\$)		0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 01/10/2024

PRECISE AUTO SERVICE (HQ) Date Inspected: 01/10/2024 Inspected At:

NO 1 KAKI BUKIT AVE 6, #02-34/36

SINGAPORE 417883

Estimated Period of Repair: 0.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: **HUEY YON** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2024)

Parts: M1-MPV TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNP9291S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >