

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS			Ref:	CS/LIP24060192/Unh3
		AY #25-01 NORTH TOWER	Date:	24/06/2024
	SINGAPORE 04858			
			Code:	LIP
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 4149G	Veh. Inspected	SMR 6513Z
	Policy No.	-	Coverage	0
	Claim No.	IVS24/1185	Excess	\$0.00
	Assign From	KAHARUDIN	Assign Date	24/06/2024
2. Vehicle Details				
	Make & Model	HONDA FIT 1.3 (A)	C.C	1317
	Engine No.	L13B3946347	Year of Reg.	16/01/2020
	Chassis No.	GK33431899	Colour	BLUE
	Odometer	263825 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM	•	
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	185/60R15	BEARWAY	6
	L/H Front Tyre	185/60R15	BEARWAY	6
	R/H Rear Tyre	185/60R15	BEARWAY	6
	L/H Rear Tyre	185/60R15	BEARWAY	6
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	20/06/2024	Inspection Date	21/06/2024
	Gurvey held at CHOO MOTOR SPRAY PAINTER - 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUK SINGAPORE 417883			
5a.	Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair