

ASS. REC. BY:

REF:

C9/C12 24100035/Kgm3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8147K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNM 8715J Yr Regn: 10, 23Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Yaris C.C. 1490Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 21407 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB AB3X01007788Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

Rear

R/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 25/9/24D.O.I. 2/10/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/10 @ 3924.85 Car Insured #4691.61, 547)

Date/Time, File Pass to?

☐ : Prel. Report

1) 16/10 Prel. Rpt

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

Excluding - 78
3924.85



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBJ417E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 25/09/2024

TP VEH REG NO : GBJ417E

ESTIMATE

NO : QUOT202409-000086(00)

DATE : 01/10/2024

POLICY NO : SP2003907937

VEH REG NO : SNM8715J

MAKE/MODEL : TOYOTA YARIS CROSS HYBRID
ACTIVE (AT) (2WD)

CHASSIS NO : JTDKBAB3X01007788

ENGINE NO : M15AY803212

REG. DATE : 2023

Estimate Repair Cost to Vehicle No : SNM8715J

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Tailgate	1	1,938.90	1,938.90
2 Tailgate 'YARIS CROSS' emblem	1	64.10	64.10
3 Tailgate 'HYBRID' emblem	1	75.00	75.00
4 Tailgate lock	1	599.65	599.65
5 Tailgate weatherstrip	1	456.00	456.00
6 Rear end panel	1	949.60	949.60
7 Rear end panel top garnish	1	267.50	267.50
8 Rear bumper	1	627.30	627.30
9 Rear bumper lower garnish	1	678.20	678.20
10 Rear bumper sensor	2	591.80	1,183.60
11 Rear bumper sensor seal	4	55.60	222.40
12 Rear bumper clips	15	6.20	93.00
			7,155.25
		Less 25%	1,788.79
			5,366.46
SPECIAL NET			
13 Rear windscreen sealant	1	60.00	60.00
			60.00
LABOUR			
14 To remove & refix rear windscreen	1	150.00	150.00
15 To transfer damaged tailgate interior parts to new tailgate	1	120.00	120.00
16 To remove & refit rear bumper sensor	1	100.00	100.00
17 To check & rectify wiring system	1	80.00	80.00
18 To remove & refix rear interior garnishes & trimboard to facilitate the repairs	1	180.00	180.00
19 To panel beat and straighten rear chasis frame, rear floorboard panel, to cut & weld rear end panel, including replacement of parts and align where necessary, to refit & adjust the same	1	1,200.00	1,200.00
20 To putty & spray paint on affected areas	1	1,200.00	1,200.00
21 To apply rust-proofing on replaced & repaired panels	1	160.00	160.00
			3,190.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL : FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBJ417E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2023

ACCIDENT DATE : 25/09/2024

TP VEH REG NO : GBJ417E

ESTIMATE

NO : QUOT202409-000086(00)

DATE : 01/10/2024

POLICY NO : SP2003907937

VEH REG NO : SNM8715J

MAKE/MODEL : TOYOTA YARIS CROSS HYBRID
ACTIVE (AT) (2WD)

CHASSIS NO : JTDKBAB3X01007788

ENGINE NO : M15AY803212

Estimate Repair Cost to Vehicle No : SNM8715J

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 8,616.46
		ADD GST @ 9.00%	775.49
		GRAND TOTAL	S\$ 9,391.95

SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED NINETY-ONE AND CENTS NINETY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE