

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401226

INV Date : 01-11-2024

Reference CS/SMR24100038/Evp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. VKM 680

Insured Veh. SHB 1020E

Claim No. TAX/09/24/2092

Policy No.

Accident Date 26/09/2024

Inspection Date 30/09/2024

Description	Amount
Survey Inspection	128.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref: Date: Code:	CS/SMR24100038/Evp3m4 01/11/2024 SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1020E	Veh. Inspected	VKM 680
	Policy No.	-	Coverage	0
	Claim No.	TAX/09/24/2092	Excess	\$0.00
	Assign From	HUA YEN	Assign Date	30/09/2024
2. Vehicle Details				
	Make & Model	YAMAHA 135LC	C.C	134
	Engine No.	G3S8E108543	Year of Reg.	06/02/2024
	Chassis No.	PMYUG1710P0103502	Colour	GREY
	Odometer	5304 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	60/70-17	MAXXIS	5
	L/H Front Tyre			
	R/H Rear Tyre	90/80-17	MAXXIS	5
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	26/09/2024	Inspection Date	30/09/2024
	Survey held at	BL AUTOMOBILE SERVICE 25 KAKI BUKIT ROAD 4 #03-24 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO VKM 680

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT MUDGUARD	CUT	\$128.60	\$128.60
1	SET FRONT FORK	BENT	\$480.00	\$480.00
1	FRONT FORK BRACKET	BENT	\$126.70	\$126.70
1	FRONT FORK BEARING	NECESSARY	\$115.20	\$115.20
1	HEADLAMP FAIRING TOP	CUT	\$226.70	\$226.70
1	SET HEADLAMP FAIRING LOWER	CUT	\$425.60	\$425.60
1	HEADLAMP ASSY	CUT	\$325.80	\$325.80
1	SET SIDE FAIRING	CUT	\$520.00	\$520.00
1	SIDE FAIRING INNER TOP GARNISH O/S	CUT	\$148.20	\$148.20
1	SIDE SIGNAL LAMP N/S	CUT	\$175.80	\$175.80
1	SET HANDLE BAR GRIP	NOT NECESSARY	\$175.60	\$0.00
1	SET HANDLE BAR BALANCER	CUT	\$155.40	\$155.40
1	BRAKE LEVER O/S	BROKEN	\$145.20	\$145.20
1	SET WING MIRROR	BROKEN	\$195.00	\$195.00
1	BRAKE STEP PEDAL	NOT NECESSARY	\$196.20	\$0.00
1	SIDE STAND	NOT NECESSARY	\$176.40	\$0.00
1	STEP PEDAL BRACKET/BAR	NOT NECESSARY	\$226.50	\$0.00
1	SET FRONT STEP PEDAL	NOT NECESSARY	\$155.00	\$0.00
1	SET REAR SIDE FAIRING	CUT	\$405.60	\$405.60
1	SET REAR SIDE HANDLE BAR	CUT	\$175.00	\$175.00
1	REAR EXHAUST PIPE	NOT NECESSARY	\$450.20	\$0.00
1	SET REAR EXHAUST HEAT GUARD	NOT NECESSARY	\$196.80	\$0.00
	LESS 5.00 / 10.00% DISCOUNT		(\$266.28)	(\$374.88)
			\$5,059.22	\$3,373.92
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	NECESSARY	\$32.00	\$20.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00
1	SET FAIRING STICKER (SN)	NECESSARY	\$280.00	\$150.00
			\$350.00	\$170.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE, RE-ALIGN & INSTALL AFFECTED DAMAGED AREAS (\$200.00 PER DAY)	NOT NECESSARY	\$600.00	\$300.00
	TO DISCONNECT WIRE-HARNESS TO FACILITATE REPAIRS, CHECK & CONNECT FUNCTIONS		\$60.00	\$30.00
	TO ALIGN BODY CHASSIS - FRAME		\$200.00	\$0.00
	TO REMOVE WHEEL & BALANCE TO SPECIFICATIONS		\$20.00	\$20.00
	SUPPLY SPRAY PAINT MATERIAL & NECESSARY ITEMS TO RESPRAY AFFECTED BODY & FRAME		\$800.00	\$200.00
			\$1,680.00	\$550.00
GRAND TOTAL			\$7,089.22	\$4,093.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,000.00
Report Ref No: CS/SMR24100038/Evp3m4				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



SINGAPORE POLICE FORCE



T/20240926/2102

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20240926/2102

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/09/2024 19:42		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: Chai Luo Wei			Address:		
ID Type / ID No.: FIN NO / M3069616J			Contact No.: Home/Office:		Mobile:
Nationality: MALAYSIAN			Email:		
Sex: Male	Age:	Date of Birth:	Type of Informant: Rider		
Race: Chinese			Language:		
Occupation: SHENG SHIONG WORKER			Driving Licence Information: Class: 2B		Date of Expiry: 22/01/2029

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 26/09/2024 14:40	Type of Location: Straight Road
Location: TELOK BLANGAH CRESCENT				
Lamp Post Number: 47				
Weather: Sunny		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of Passenger
SHB1020E	Motor car				Slightly Damaged	1
VKM680	Motorcycle				Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20240926/2102

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20240926/2102

CONTINUATION OF REPORT

Brief Details.

I am here to lodge a police report to claim for insurance purposes.

As I was riding my motorcycle (VKM680) along Henderson Road on the second lane, I was sideswiped by a maroon taxi (SHB1020E). As he was switching into my lane, he did not signal. Thus, there was not enough time for me to avoid him. Hence, the left side of the taxi knocked into me, and I fell off my motorcycle.

I suffered the following injuries:

Cuts on my both knuckles, right forearm and on my left thigh. Abrasion on my left elbow.

My motorcycle also had been damaged from the accident. Both side mirror of my motorcycle broke off, IU unit, engine leaked (causing black oil spillage), scratches on the front bonnet and scratches on part of the body kit.

That is all.



**SINGAPORE
POLICE FORCE**



T/20240926/2102

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20240926/2102

CONTINUATION OF REPORT

Signature of Officer Recording The
A /
SCCPL OOI YI ZHE

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SR STAFF SGT FAHKRUL RAZI BIN SUHAIME
Contact No.: 65476404

Signature Of Informant:

Date/Time:
26/09/2024 19:42

Classification Of Case:



T/20240927/2078

1 of 2

Report No. T/20240927/2078

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No	-
Report Number	T/20240927/2078
Vide Report Number	T/20240926/2102
Date/Time of Report Made	27/09/2024 17:54
Place Report Lodged	Traffic Police
Type of Informant	Rider
Name of Informant	CHAI LUO WEI
ID Type / ID No.	FIN NO / M3069616J
Home/Office	0
Mobile	85877118
Email	
Type of Accident	Injury / Foreign Vehicle
Drink Drive	No
Anyone conveyed by ambulance	No
Date/Time of Accident	26/09/2024 14:40

Brief Facts.

With reference to NP168 (T/20240926/2102), the correct brief facts should be

I am here to lodge a police report to claim for insurance purposes.

As I was riding my motorcycle (VKM680) along Henderson Road on the third lane. I was side swiped by a maroon taxi (SHB1020E). As he was switching lane, he did not signal. Thus, there was not enough time for me to avoid him. Hence, the left side of the taxi knocked into me, and I fell off my motorcycle.

I suffered the following injuries:
Cuts on my both knuckles, right forearm and on my left thigh. Abrasion on my left elbow.



T/20240927/2078

2 of 2

Report No. T/20240927/2078

Continuation of CSF For NP168

My motorcycle also had been damaged from the accident. Both side mirror of my motorcycle broke off, IU unit, engine leaked (causing black oil spillage), scratches on the front bonnet and scratches on part of the body kit.

That is all.

Case Sensitivity

No

Officer-In-Charge of Case

TP / AEIT /
FAHKRUL RAZI BIN SUHAIME

Classification of Case

1) INJURY / FOREIGN VEHICLE

PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680





PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 20 of 20)

PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680





PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680




PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680



PHOTOGRAPHS FOR VEHICLE NO. : VKM 680

