

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24100041/KVP3E2
Date: 18/10/2024REFERENCE**Insured/Claimant:** NIRMAWATI BANTE ABDUL RAHMAN **Policy No:** MPC24A00005000
Date of Loss: 29/09/2024 **Nature of Claim:** OD **Claim No:** DMPC2401311H/STDESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SLA284A **Engine No:** FB161647302
Make & Model: SUBARU XV, 1.6 (A) **Chassis No:** JF1GP3KC5FG151041
Reg. Date: 22/01/2016 (Man. Year: 2015) **Odometer:** 119256 km
Colour: Metallic Pearl White
Engine Capacity: 1600 cc
Market Value/New Car Price: S\$26,000.00
Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size:** 225/55 R17 **Rear Tyre Size:** 225/55 R17
Front Left Side: Goodyear 8 mm **Rear Left Side:** Goodyear 8 mm
Front Right Side: Goodyear 8 mm **Rear Right Side:** Goodyear 8 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,487.80	4,647.50	1,840.30	28.37
Miscellaneous Items	330.00	275.00	55.00	16.67
Labour	2,820.00	1,820.00	1,000.00	35.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,637.80	6,742.50	2,895.30	30.04
Approved Total (Overridden) (\$\$)		5,400.00		
(\$\$)	9,637.80	5,400.00	4,237.80	43.97
+ GST 9.00/9.00% (\$\$)	867.40	486.00	381.40	43.97
Nett Amount (\$\$)	10,505.20	5,886.00	4,619.20	43.97

INSPECTION**Date of Assignment:** 02/10/2024 **Present Location:** Accord Auto Services Pte Ltd (HQ)
Date Inspected: 02/10/2024 **Inspected At:** Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047
Estimated Period of Repair: 6.0 days**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2024)
Parts:	144	SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA284A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Bent	800.00 F	*800.00 F
2	2		*FRONT BONNET HINGE (WCP)	Distorted	120.00 F	*120.00 F
3	1		*FRONT GRILLE BASE (WCP)	Serviceable	95.00 F	*- F
4	1		*FRONT GRILLE CHROME *SURROUND (WCP)	Dented	140.00 F	*140.00 F
5	1		*FRONT EMBLEM (WCP)	Necessary	45.00 F	*45.00 F
6	1		*FRONT GRILLE CHROME *CENTRE (WCP)	Cracked	80.00 F	*80.00 F
7	1		*FRONT BUMPER (WCP)	Cracked	290.00 F	*290.00 F
8	2		*FRONT BUMPER SIDE RETAINER LH & RH (WCP)	Distorted	60.00 F	*60.00 F
9	1		*FRONT HEADLAMP RH (WCP)	Missing	580.00 F	*580.00 F
10	1		*FRONT HEADLAMP LOWER BRACKET RH (WCP)	Cracked	40.00 F	*40.00 F
11	1		*FRONT FOGLAMP RH (WCP)	Missing	250.00 F	*250.00 F
12	1		*FRONT FOGLAMP LH (WCP)	Mtg Cracked	250.00 F	*250.00 F
13	1		*FRONT BUMPER SPONGE (WCP)	Broken	45.00 F	*45.00 F
14	1		*FRONT REINFORCEMENT (WCP)	Bent	160.00 F	*160.00 F
15	1		*FRONT BUMPER TOW COVER (WCP)	Serviceable	8.00 F	*- F
16	1		*FRONT FENDER RH (WCP)	Bent	200.00 F	*200.00 F
17	1		*FRONT FENDER INNER SHIELD RH (WCP)	Torn	90.00 F	*90.00 F
18	1		*FRONT WHEEL ARCH RH (WCP)	Buckled	70.00 F	*70.00 F
19	1		*FRONT FENDER TOP MOULDING RH (WCP)	Distorted	150.00 F	*150.00 F
20	1		*FRONT FENDER LH (WCP)	Buckled	160.00 F	*160.00 F
21	1		*FRONT FENDER INNER SHIELD LH (WCP)	Cracked	90.00 F	*90.00 F
22	1		*FRONT FENDER TOP MOULDING LH (WCP)	Serviceable	150.00 F	*- F
23	1		*FRONT WINDSCREEN GARNISH RH (WCP)	Serviceable	80.00 F	*- F
24	1		*RADIATOR (WCP)	Twisted / Punctured	400.00 F	*400.00 F
25	1		*RADIATOR FAN MOTOR (WCP)	Serviceable	150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*RADIATOR FAN COWLING (WCP)	Serviceable	90.00 F	*- F
27	2		*RADIATOR STOPPER LOWER (WCP)	Serviceable	20.00 F	*- F
28	1		*RADIATOR STOPPER TOP (WCP)	Serviceable	30.00 F	*- F
29	1		*RADIATOR TOP HOSE (WCP)	Serviceable	45.00 F	*- F
30	1		*RADIATOR LOWER HOSE (WCP)	Serviceable	45.00 F	*- F
31	1		*AIR CLEANER BOX (WCP)	Mtg Cracked	35.00 F	*35.00 F
32	2		*AIR CLEANER BOX AIR DUCT (WCP)	Mtg Cracked	170.00 F	*170.00 F
33	1		*FRONT DOOR RH (WCP)	Repair	500.00 F	*- F
34	2		*FRONT DOOR HINGE RH (WCP)	Repair	140.00 F	*- F
35	1		*FRONT DOOR CHECKER RH (WCP)	Serviceable	30.00 F	*- F
36	1		*FRONT DOOR RUBBER RH (WCP)	Serviceable	250.00 F	*- F
37	1		*FRONT DOOR STICKER RH SET (WCP)	Not Necessary	40.00 F	*- F

F=Franchise part.

Sub Total (S\$)	5,898.00	4,225.00
+ Margin on L,N Items 10.00/10.00% (S\$)	589.80	422.50
Total Parts (S\$)	6,487.80	4,647.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	FRONT DOOR INNER COMPARTMENT CLIPS (NOT NECESSARY)	50.00	0.00
3	2	FRONT FENDER INNER SHILED LH & RH (NECESSARY)	180.00	180.00
4	1	FRONT NUMBER PLATE WITH HOLDER (DISTORTED)	50.00	45.00
Sub Total (\$\$)			330.00	275.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,200.00	1,000.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	800.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	20.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
5	TO REMOVE/REFIX/REPLACE FRONT RH DOOR GLASS, INNER COMPARTMENT, MECEMISM & ETC TO NEW DOOR	New	200.00	0.00
Gross Labour Cost (\$\$)			2,820.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >