

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24A00005000	Date of Loss:	29/09/2024
Vehicle Reg. No.:	SLA284A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NIRMAWATI BANTE ABDUL RAHMAN		
Driver:	ABDUL RAHMAN AHMAD ZAINI		
Make/Model:	SUBARU XV, 1.6 (A)	Vehicle Reg. Date:	22/01/2016
Vehicle Colour:	WHITE	Chassis No:	JF1GP3KC5FG151041
Engine No:	FB161647302		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6 ✓		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

Not Whaired
1/1 Rng &
Repairing After Paint
EX TBA

COST OF CLAIMS

	Amount
Parts	6,487.80
Miscellaneous Items	330.00
Labour	2,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,637.80
+ GST 9.00% (\$\$)	867.40
Nett Amount (\$\$)	10,505.20

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2024)
 Parts: 144 SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	0.00	0.00	<i>By</i> *800.00 F	✓
2	2		*FRONT BONNET HINGE	0.00	0.00	<i>Di</i> *120.00 F	✓
3	1		*FRONT GRILLE BASE	0.00	0.00	*95.00 F	?
4	1		*FRONT GRILLE CHROME *SURROUND	0.00	0.00	<i>Di</i> *140.00 F	?
5	1		*FRONT EMBLEM	0.00	0.00	<i>Di</i> *45.00 F	?
6	1		*FRONT GRILLE CHROME *CENTRE	0.00	0.00	<i>CM</i> *80.00 F	?
7	1		*FRONT BUMPER	0.00	0.00	<i>CM</i> *290.00 F	✓
8	2		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	<i>Di</i> *60.00 F	✓
9	1		*FRONT HEADLAMP RH	0.00	0.00	<i>Di</i> *580.00 F	✓
10	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	<i>CM</i> *40.00 F	—
11	1		*FRONT FOGLAMP RH	0.00	0.00	<i>Di</i> *250.00 F	✓
12	1		*FRONT FOGLAMP LH	0.00	0.00	*250.00 F	?
13	1		*FRONT BUMPER SPONGE	0.00	0.00	<i>Br</i> *45.00 F	✓
14	1		*FRONT REINFORCEMENT	0.00	0.00	<i>By</i> *160.00 F	✓
15	1		*FRONT BUMPER TOW COVER	0.00	0.00	<i>Di</i> *8.00 F	X
16	1		*FRONT FENDER RH	<i>By</i> 0.00	0.00	*200.00 F	✓
17	1		*FRONT FENDER INNER SHIELD RH	<i>Di</i> 0.00	0.00	*90.00 F	✓
18	1		*FRONT WHEEL ARCH RH	0.00	0.00	<i>Br</i> *70.00 F	✓
19	1		*FRONT FENDER TOP MOULDING RH	<i>Di</i> 0.00	0.00	*150.00 F	✓
20	1		*FRONT FENDER LH	<i>Br</i> 0.00	0.00	*160.00 F	✓
21	1		*FRONT FENDER INNER SHIELD LH	<i>CM</i> 0.00	0.00	*90.00 F	✓
22	1		*FRONT FENDER TOP MOULDING LH	<i>Di</i> 0.00	0.00	*150.00 F	X
23	1		*FRONT WINDSCREEN GARNISH RH	0.00	0.00	<i>Di</i> *80.00 F	X
24	1		*RADIATOR	0.00	0.00	*400.00 F	?
25	1		*RADIATOR FAN MOTOR	0.00	0.00	<i>Di</i> *150.00 F	X
26	1		*RADIATOR FAN COWLING	0.00	0.00	<i>Di</i> *90.00 F	X
27	2		*RADIATOR STOPPER LOWER	0.00	0.00	*20.00 F	?
28	1		*RADIATOR STOPPER TOP	0.00	0.00	*30.00 F	?
29	1		*RADIATOR TOP HOSE	0.00	0.00	<i>Di</i> *45.00 F	X
30	1		*RADIATOR LOWER HOSE	0.00	0.00	<i>Di</i> *45.00 F	X
31	1		*AIR CLEANER BOX	<i>Merimen</i> 0.00	0.00	*35.00 F	✓
32	2		*AIR CLEANER BOX AIR DUCT	0.00	0.00	*170.00 F	?
33	1		*FRONT DOOR RH	0.00	0.00	<i>Di</i> *500.00 F	X
34	2		*FRONT DOOR HINGE RH	0.00	0.00	<i>Di</i> *140.00 F	X
35	1		*FRONT DOOR CHECKER RH	0.00	0.00	<i>Di</i> *30.00 F	X
36	1		*FRONT DOOR RUBBER RH	0.00	0.00	<i>Di</i> *250.00 F	X
37	1		*FRONT DOOR STICKER RH SET	0.00	0.00	<i>Di</i> *40.00 F	X

F=Franchise part.

Sub Total (\$\$) 5,898.00
 + Margin on L,N Items 10.00% (\$\$) 589.80
 Total Parts (\$\$) 6,487.80

Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	M 50.00 ✓
2	1	FRONT DOOR INNER COMPARTMENT CLIPS	N 50.00 X
3	2	FRONT FENDER INNER SHILED LH & RH	M 180.00 ✓
4	1	FRONT NUMBER PLATE WITH HOLDER	DIT 50.00 45.00
Sub Total (\$\$)			330.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1000 1,200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800 1,200.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	20 100.00
4	TO APPLY ANTI RUST TREATMENT	New	NZ 120.00 X
5	TO REMOVE/REFIX/REPLACE FRONT RH DOOR GLASS, INNER COMPARTMENT, MECHHEMISM & ETC TO NEW DOOR	New	N 200.00 X
Gross Labour Cost (\$\$)			2,820.00

Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: