10/14/24, 3:44 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24100042/UQP3E2

HR12166801B

Date: 14/10/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1000849949

Claimant Vehicle No: SLA4495G

SLA4495G

Insured Vehicle No: SJY1113B

Date of Loss: 28/09/2024 Nature of Claim: TP Claim No: 375196

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA4495G

Make & Model: NISSAN NOTE, 1.2 CVT ABS D/AIRBAG 2WD Engine No:

5DR DIG-S (A)

Reg. Date: 29/02/2016 (Man. Year: 2016) Chassis No: JN1TAAF1270972169

Reg. Date: 29/02/2016 (Man. Year: 2016) Chassis No: JN1TAAE12Z Colour: White Odometer: 45162 km

Colour: White Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,758.20	777.90	6,980.30	89.97
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,710.00	1,230.00	1,480.00	54.61
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,468.20	2,007.90	8,460.30	80.82
	Approved Total (Overridden) (S\$)		1,600.00		
	(S\$)	10,468.20	1,600.00	8,868.20	84.72
	+ GST 9.00/9.00% (S\$)	942.14	144.00	798.14	84.72
	Nett Amount (S\$)	11,410.34	1,744.00	9,666.34	84.72

<u>INSPECTION</u>

Date of Assignment: 01/10/2024

SPEEDWERKZ PTE LTD (Autobay) (HQ)

Date Inspected: 02/10/2024 Inspected At: 1 KAKI BUKIT AVENUE 6 #01-73

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/14/24, 3:44 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2024)

Parts: 144 NISSAN NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR DIG-S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA4495G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,661.90 FN	*- FN
2	1		*TAILGATE LOGO	Necessary	68.60 FN	*68.60 FN
3	1		*TAILGATE NOTE EMBLEM	Necessary	79.90 FN	*79.90 FN
4	2		*TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	188.80 FN	*- FN
5	1		*TAILGATE OUTER HANDLE	Not Necessary	312.10 FN	*- FN
6	1		*TAILGATE INNER LOCK	Not Necessary	283.60 FN	*- FN
7	1		*TAILGATE STRIKER	Not Necessary	56.20 FN	*- FN
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	182.60 FN	*- FN
9	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	82.60 FN	*- FN
10	1		*TAILGATE INNER TRIMBOARD	Not Necessary	311.20 FN	*- FN
11	1		*TAILGATE INNER PULL POCKET	Not Necessary	86.90 FN	*- FN
12	2		*TAIL LAMP L/R	Not Necessary	1,186.40 FN	*- FN
13	1		*REAR BUMPER	Dented / Cracked	667.00 FN	*579.90 FN
14	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	166.40 FN	*- FN
15	2		*REAR BUMPER SIDE BRACKET L/R	Not Necessary	210.00 FN	*- FN
16	1		*REAR BUMPER SPONGE	Torn	162.60 FN	*102.60 FN
17	1		*REAR ANTENNA	Not Necessary	181.20 FN	*- FN
18	1		*END PANEL	Repair	712.10 FN	*- FN
19	1		*END PANEL GARNISH	Not Necessary	142.30 FN	*- FN
20	2		*REAR FENDER INNER TRIMBOARD L/R	Not Necessary	1,055.60 FN	*- FN
21	1		*REAR REVERSE SENSOR	Serviceable	280.00 FS	*- FS
22	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*TAILGATE TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*TAILGATE CHROME GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
26	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
27	2		*REAR FENDER INNER TRIMBOARD L/R CLIPS	Not Necessary	160.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	lett. N=NettItemDisc.	_		
				Sub Total (S\$)	8,538.00	861.00
	- Nett Item Discount on N Items 10.00/10.00% (S\$)			779.80	83.10	
				Total Parts (S\$)	7,758.20	777.90

Report was unsubmitted during this print-out.

10/14/24, 3:44 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REFIX REAR REVERSE SENSOR	New	80.00	30.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	100.00	0.00
4	TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW	New	100.00	0.00
5	TO PROVIDE LABOUR, WORKMANSHIP	New	1,200.00	580.00
6	TO SPRAY PAINT ON AFFECTED PANELS	New	1,000.00	600.00
7	RUST PROOFING	New	180.00	0.00
		Gross Labour Cost (S\$)	2,710.00	1,230.00
	Report was unsubmitte	and during this print out		

< END OF ESTIMATES >