

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SLA4495G
MAKE & MODEL: NISSAN NOTE

Not Authorized
2/10/24
2/3 \$1600
take photo after repair
3 days.

TAILGATE
TAILGATE LOGO
TAILGATE "NOTE" EMBLEM
TAILGATE NUMBER PLATE LAMP L/R X2
TAILGATE OUTER HANDLE
TAILGATE INNER LOCK
TAILGATE STRIKER
TAILGATE WEATHERSTRIP
TAILGATE WINDSCREEN MOULDING
TAILGATE INNER TRIMBOARD
TAILGATE INNER PULL POCKET
TAIL LAMP L/R X2
REAR BUMPER
REAR BUMPER SIDE RETAINER L/R X2
REAR BUMPER SIDE BRACKET L/R X2
REAR BUMPER SPONGE
REAR ANTENNA
END PANEL
END PANEL GARNISH
REAR FENDER INNER TRIMBOARD L/R X2

Nett Item
R \$1,661.90 X
net \$68.60 ✓
net \$79.90 ✓
11 \$188.80 X
11 \$312.10 X
11 \$283.60 X
11 \$56.20 X
11 \$182.60 X
11 \$82.60 X
11 \$311.20 X
11 \$86.90 X
11 \$1,186.40 X
579.90 2/10/24 \$667.00 ✓
11 \$166.40 X
11 \$210.00 X
102.60 11 \$162.60 ✓
11 \$181.20 X
R \$712.10 X
11 \$142.30 X
11 \$1,055.60 X
\$7,798.00
Less 10% \$779.80
\$7,018.20

REAR REVERSE SENSOR
REAR BUMPER CLIPS
TAILGATE TRIMBOARD CLIPS
TAILGATE CHROME GARNISH CLIPS
END PANEL GARNISH CLIPS
END PANEL SEALANT
REAR FENDER INNER TRIMBOARD L/R CLIPS X2

See \$280.00 X
11 \$60.00 30 5/12
11 \$50.00 X
11 \$30.00 X
11 \$60.00 X
11 \$100.00 X
11 \$160.00 X
\$740.00

TO CHECK REAR WIRING
TO REPLACE REAR REVERSE SENSOR
TO REMOVE AND REFIT REAR REVERSE CAMERA
TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW
TO PROVIDE LABOUR, WORKMANSHIP
TO SPRAY PAINT ON AFFECTED PANELS
RUST PROOFING

\$50.00 20
\$80.00 30
11 \$100.00 X
11 \$100.00 X
\$1,200.00 580
\$1,000.00 600
11 \$180.00 X
\$2,710.00
\$10,468.20

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) under resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1-831.
102
147.90
30
1230
2007.9
1606