

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100046/UUA3Q2
Date: 06/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : GBF238B Insured Vehicle No : SLF5470U
Date of Loss: 25/09/2024 Nature of Claim: TP Claim No: MFL2024D0011296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF238B
Make & Model: FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M) Engine No: 263A50007584829
Reg. Date: 25/05/2016 (Man. Year: 2016) Chassis No: ZFA26300006C06696
Colour: White Odometer: 158708 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Maxmiler 6 mm Rear Left Side: Lassa 6 mm
Front Right Side: Maxmiler 6 mm Rear Right Side: Lassa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,023.40	4,667.06	4,356.34	48.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,480.00	1,340.00	47.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,843.40	6,147.06	5,696.34	48.10
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	11,843.40	4,900.00	6,943.40	58.63
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,287.25		

INSPECTION

Date of Assignment: 03/10/2024
Date Inspected: 03/10/2024 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF238B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAILGATE	Repair	1,895.90 F	*- FL
2	1		*REAR RH TAILGATE WEATHERSTRIP	Not Necessary	297.00 F	*- FL
3	1		*REAR RH TAILGATE LOCK LOWER	Not Necessary	192.90 F	*- FL
4	1		*REAR RH TAILGATE OUTER GARNISH	Cracked	321.80 F	*288.00 FL
5	1		*REAR RH TAILGATE FIAT EMBLEM	Not Necessary	87.80 F	*- FL
6	1		*REAR RH TAILGATE FIAT EMBLEM	Not Necessary	87.80 F	*- FL
7	1		*REAR RH TAILGATE PROFFESIONAL EMBLEM	Necessary	163.50 F	*148.00 FL
8	1		*REAR RH TAILGATE 6 PAX STICKER	Necessary	15.00 FS	*10.00 FS
9	1		*REAR RH TAILGATE MULTIJET EMBLEM	Necessary	92.00 F	*92.00 FL
10	1		*REAR RH TAILGATE 90 EMBLEM	Necessary	97.50 F	*97.50 FL
11	1		*REAR RH TAILGATE GLASS SEALANT	Not Necessary	80.00 FS	*- FS
12	1		*REAR LH TAILGATE	Dented / Bent	2,156.30 F	*1,820.00 FL
13	1		*REAR LH TAILGATE WEATHERSTRIP	Not Necessary	344.50 F	*- FL
14	1		*REAR LH TAILGATE LOCK LOWER	N/S Damaged	385.80 F	*192.90 FL
15	1		*REAR LH TAILGATE NUMBER LATE GARNISH	Cracked	279.00 F	*279.00 FL
16	2		*REAR LH TAILGATE NUMBER PLATE LAMP	Not Necessary	103.00 F	*- FL
17	1		*REAR LH TAILGATE DOBLO EMBLEM	Necessary	105.00 F	*105.00 FL
18	1		*REAR LH TAILGATE MAXI EMBLEM	Necessary	90.00 F	*90.00 FL
19	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
20	1		*REAR LH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*REAR BUMPER	Dented / Deformed	745.00 F	*745.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
23	1		*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
24	1		*REAR BUMPER REVERSE SENSOR	Malfunction	220.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE & BASE	Serviceable	48.00 FS	*- FS
26	1		*REAR LH BUMPER REFLECTOR	Cracked	117.60 F	*68.00 FL
27	1		*REAR LH TAIL LAMP	Cracked	462.70 F	*462.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,023.40	5,153.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	486.34
Total Parts (\$\$)	9,023.40	4,667.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL REAR RH & LH WINDSCREEN GLASS TO FACILITATE REPAIRS	New	240.00	100.00
2	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISM	New	180.00	50.00
3	REMOVE AND REPLACED REAR REVERSE SENSOR	New	100.00	30.00
4	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	120.00	20.00
5	LABOR FOR PANEL BEATING ,CUT ,WELD STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	550.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	900.00	700.00
7	TO APPLY RUST PROOFING RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
Gross Labour Cost (\$\$)			2,820.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >