

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/1124100046/Uua3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF238B

at Workshop m/s

100's 30

of

Insured:

SLF 54704

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

815k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

LIA 55747

Vehicle: IN / OUT

Veh No:

GBF238B

Yr Regn:

25/95/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

ZIA7 206to

c.c 1598

Colour

Wh-Br

A/C: Insured / Std / NI / NA

Sp. Reading

158708

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2FA26300006C0 6696

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

Maxmiller
195/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Lessy

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/09/24

D.O.I.

03/10/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/10/24 1/5 @ 4900 Dep 8100
inform Susan

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I R I / \$

**Liu's Brother Auto Engineering Workshop**

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: India International Insurance Pte Ltd

Ref Date:

02/10/2024

Address Motor Claims Department

Ref No:

GBF238B240925

64 Cecil Street #04-00 & #05-00

Vehicle No:

GBF238B

IOB Building

Singapore 049711

Model / Make:

Fiat Doblo

Maxi 1.6 MTJ AMT Glaze

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear Rh	Tailgate	\$ 1,895.90	1	\$ 1,895.90		2X
2		Tailgate Weatherstrip	\$ 297.00	1	\$ 297.00		1X
3		Tailgate Lock Lower	\$ 192.90	1	\$ 192.90		1X
4		Tailgate Outer Garnish 288.00	\$ 321.80	1	\$ 321.80		Che ✓
5		Tailgate "Fiat" Emblem	\$ 87.80	1	\$ 87.80		1X
6		Tailgate "Fiat" Emblem	\$ 87.80	1	\$ 87.80		1X
7		Tailgate "Professional" Emblem 148.00	\$ 163.50	1	\$ 163.50		new ✓
8		Tailgate "6 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	new 105/N
9		Tailgate "MULTIJET" Emblem	\$ 92.00	1	\$ 92.00		new ✓
10		Tailgate "90" Emblem	\$ 97.50	1	\$ 97.50		new ✓
11		Tailgate Glass Sealant	\$ 80.00	1	\$ 80.00	SN	1X
12	Rear Lh	Tailgate 820	\$ 2,156.30	1	\$ 2,156.30		20/304 ✓
13		Tailgate Weatherstrip	\$ 344.50	1	\$ 344.50		1X
13		Tailgate Lock Lower	\$ 192.90	2	\$ 385.80		new 1pc
20		Tailgate Number Plate Garnish	\$ 279.00	1	\$ 279.00		Che ✓
21		Tailgate Number Plate Lamp	\$ 51.50	2	\$ 103.00		1X
8		Tailgate "DOBLO" Emblem	\$ 105.00	1	\$ 105.00		new ✓
9		Tailgate "Maxi" Emblem	\$ 90.00	1	\$ 90.00		new ✓
18		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	new 105/N
17		Tailgate Glass Sealant	\$ 80.00	1	\$ 80.00	SN	new 405/N
19	Rear	Bumper	\$ 745.00	1	\$ 745.00		20/02 ✓
20		Bumper Clips 1 set	\$ 65.00	1	\$ 65.00	SN	new 305/N
21		Bumper Reinforcement	\$ 475.30	1	\$ 475.30		new ✓
22		Bumper Reverse Sensor	\$ 220.00	1	\$ 220.00	SN	new 2005/N
47		Number Plate & Base	\$ 48.00	1	\$ 48.00	SN	new X
23	Rear Lh	Bumper Reflector 68.00	\$ 117.60	1	\$ 117.60		Che ✓
40		Tail Lamp	\$ 462.70	1	\$ 462.70		Che ✓
48		Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs			\$ 240.00		\$ - 100/1pc
49		Remove and refix rear Rh & Lh tailgate components & wiper mechanism			\$ 180.00		\$ - 50 1pc
50		Remove and refix rear reverse sensor			\$ 100.00		\$ - 30
51		To check all wiring & electrical component for proper function			\$ 120.00		\$ - 20
54		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,200.00		\$ - 550
55		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		\$ - 700
56		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 80.00		\$ - 30

Total Parts & Labour of estimate for damaged vehicle

\$ 11,843.40

Total amount in Lumpsum Basis for repaired vehicle

SDL

- hence notify the Repairer of the following:
- To resurvey before spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Liu's Bro Auto Engrg Wks

P- 4863-4
102

4377-06

290