



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100054/Anp3e2
(BUDGET DIRECT INSURANCE)	Date:	20/11/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 3561Z	Veh. Inspected	SLP 3801J
Policy No.	P10826894R01	Coverage	0
Claim No.	C10032015/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	02/10/2024

2. Vehicle Details

Make & Model	HONDA STREAM	C.C	1799
Engine No.	R18A1793238	Year of Reg.	23/03/2009
Chassis No.	RN61084050	Colour	SILVER
Odometer	212010 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45 R17	APLUS	6
L/H Front Tyre	215/45 R17	APLUS	6
R/H Rear Tyre	215/45 R17	APLUS	6
L/H Rear Tyre	215/45 R17	APLUS	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/09/2024	Inspection Date	02/10/2024
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 21 Working Days