



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SBK 969Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH DOOR	DENTED	\$1,780.00	\$1,780.00
1	FRONT LH DOOR HINGE (LOWER)	NOT NECESSARY	\$105.00	\$0.00
1	FRONT LH DOOR HINGE (TOP)	NOT NECESSARY	\$105.00	\$0.00
1	FRONT LH DOOR MECHANISM LOCK	NOT NECESSARY	\$369.00	\$0.00
1	FRONT LH DOOR PROTECTOR	CUT	\$405.00	\$405.00
1	FRONT LH DOOR PROTECTOR OUTER CHROME MOULDING	CUT	\$289.00	\$289.00
1	FRONT LH DOOR WEATHER STRIP	NECESSARY	\$278.00	\$278.00
1	REAR BUMPER SIDE COVER LH	TO REPAIR SEE LABOUR	\$296.00	\$0.00
1	REAR LH DOOR	DENTED	\$1,789.00	\$1,789.00
1	REAR LH DOOR HINGE (LOWER)	NOT NECESSARY	\$105.00	\$0.00
1	REAR LH DOOR HINGE (TOP)	NOT NECESSARY	\$105.00	\$0.00
1	REAR LH DOOR MECHANISM LOCK	NOT NECESSARY	\$356.00	\$0.00
1	REAR LH DOOR PROTECTOR	CUT	\$415.00	\$415.00
1	REAR LH DOOR PROTECTOR OUTER CHROME MOULDING	CUT	\$288.00	\$288.00
1	REAR LH DOOR WEATHER STRIP	NOT NECESSARY	\$298.00	\$0.00
1	REAR LH DOOR WEATHER STRIP (VERTICAL)	NOT NECESSARY	\$125.00	\$0.00
1	REAR LH FENDER ARCH GARNISH	CUT	\$449.00	\$449.00
1	REAR LH SPORT RIM	CUT	\$1,792.00	\$1,792.00
1	REAR LH WHEEL BEARING	NOT NECESSARY	\$469.00	\$0.00
	LESS 10.00% DISCOUNT		(\$981.80)	(\$748.50)
			\$8,836.20	\$6,736.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT LH DOOR PROTECTOR CLIPS (SN)	NECESSARY	\$50.00	\$20.00
1	SET REAR LH DOOR PROTECTOR CLIPS (SN)	NECESSARY	\$50.00	\$20.00
1	SET REAR LH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	\$40.00	\$20.00
1	REAR LH TYRE (SN)	NOT NECESSARY	\$400.00	\$0.00
			\$540.00	\$60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	NOT NECESSARY	\$200.00	\$0.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE		\$160.00	\$120.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,000.00	\$600.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE COVER LH		\$800.00	\$400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$120.00	\$0.00
			\$2,380.00	\$1,200.00
GRAND TOTAL			\$11,756.20	\$7,996.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$6,400.00
Report Ref No: CS/AGI24100055/Avp3e2				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.