

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS3/FCI24100061/Eqp3e2	
	16 RAFFLES QUAY		Date:	07/10/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHC 7113B	Veh. Inspected	FBP 2835L	
	Policy No.	D-24101860MFCT	Coverage	0	
	Claim No.	D24008324MFCT	Excess	\$0.00	
	Assign From	HARMINDER	Assign Date	02/10/2024	
2. Vehicle Details					
	Make & Model	HONDA CB400	C.C	399	
	Engine No.	NC421901308	Year of Reg.	11/03/2019	
	Chassis No.	NC42E1401307	Colour	GREEN	
	Odometer	- KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	120/70Z R17	BRIDGESTONE	5	
	L/H Front Tyre				
	R/H Rear Tyre	160/70Z R17	BRIDGESTONE	5	
	L/H Rear Tyre				
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
5.	General Information				
	Accident Date	18/09/2024	Inspection Date	02/10/2024 (15:34)	
	Survey held at 71 WOODLANDS AVE 10 #01-17 - REPAIRER: M2 GARAGE PTE LTD				
5a.					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$12,000.00 E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

CTY

STEVE CHEN TSUE YEE