

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG24100062/KVP3E2
Date: 11/11/2024REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000002767
Claimant Vehicle No :	SND4238T	Insured Vehicle No :	SMR4839Y
Date of Loss:	30/09/2024	Nature of Claim:	TP
		Claim No:	8092195870SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND4238T		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	1NZ9360894
Reg. Date:	29/12/2021 (Man. Year: 2021)	Chassis No:	JTDZZ9H300L000935
Colour:	Metallic Pearl White	Odometer:	169516 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,970.86	14,304.41	24,666.45	63.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	3,080.00	2,490.00	44.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,540.86	17,384.41	27,156.45	60.97
Approved Total (Overridden) (S\$)		13,900.00		
Nett Amount (S\$)	44,540.86	13,900.00	30,640.86	68.79

INSPECTION

Date of Assignment:	02/10/2024	
Date Inspected:	03/10/2024	Inspected At: Blk 5034 Ang Mo Kio Industrial Park 2 #01-341
Estimated Period of Repair:	11.0 days	Repairer: Jd Motorsports Pte Ltd (HQ)

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,304.92 F	*1,304.92 FL
2	2		*FRONT BONNET HINGE	Distorted	249.70 F	*249.70 FL
3	1		*FRONT BONNET LOCK	Distorted	139.30 F	*139.30 FL
4	1		*FRONT BONNET INSULATOR	Serviceable	249.96 F	*- FL
5	1		*FRONT BUMPER	Buckled	1,465.00 F	*718.20 FL
6	2		*FRONT BUMPER SIDE RETAINER	Distorted	160.12 F	*160.12 FL
7	1		*FRONT BUMPER SPONGE	Cracked	311.16 F	*311.16 FL
8	2		*FRONT BUMPER FOG LAMP COVER	Serviceable	211.90 F	*- FL
9	2		*FRONT BUMPER SIDE OUTER MOULDING	Serviceable	782.96 F	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Repair	740.25 F	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Cracked	1,751.64 F	*381.60 FL
12	2		*FRONT LH BUMPER LOWER GRILLE OUTER MOULDING	Serviceable	351.60 F	*- FL
13	1		*FRONT RH BUMPER LOWER GRILLE OUTER MOULDING	Cracked	351.60 F	*351.60 FL
14	1		*FRONT BUMPER UNDER COVER	Serviceable	461.76 F	*- FL
15	1		*FRONT BUMPER EMBLEM	Necessary	197.24 F	*197.24 FL
16	1		*ENGINE UNDER SIDE SHIELD	Serviceable	336.28 F	*- FL
17	2		*FRONT HEADLAMP	Mtg Cracked	2,829.20 F	*2,566.40 FL
18	1		*SUPPORT PANEL	Buckled	1,460.52 F	*1,207.00 FL
19	1		*SUPPORT PANEL TOP GARNISH	No such part	227.48 F	*- FL
20	1		*SUPPORT PANEL TOP GARNISH RUBBER	Serviceable	27.46 F	*- FL
21	1		*BRACE PANEL	Bent	149.56 F	*149.56 FL
22	1		*SUPPORT AIR DUCT RH	Dented	73.28 F	*73.28 FL
23	1		*SUPPORT AIR DUCT LH	Serviceable	68.24 F	*- FL
24	1		*RADIATOR	Serviceable	1,025.40 F	*- FL
25	1		*A/C CONDENSER	Bent	956.30 F	*956.30 FL
26	1		*TAIL GATE	Bent	2,070.40 F	*1,081.70 FL
27	2		*TAIL GATE HINGES	Repair	470.80 F	*- FL
28	2		*TAIL GATE ABSORBER	Serviceable	757.00 F	*- FL
29	1		*TAIL GATE TRIMBOARD	Buckled	590.30 F	*590.30 FL
30	1		*TAIL GATE OUTER MOULDING	No such part	365.90 F	*- FL
31	1		*TAIL GATE OUTER HANDLE	Mtg Cracked	245.20 F	*245.20 FL
32	1		*TAIL GATE EMBLEM (HYBRID)	Necessary	184.90 F	*184.90 FL
33	1		*TAIL GATE EMBLEM (LOGO)	Necessary	230.60 F	*230.60 FL
34	1		*TAIL GATE INNER LOCK	Jammed	591.90 F	*420.80 FL
35	1		*TAIL GATE CATCH LOCK	Repair	155.70 F	*- FL
36	1		*TAIL GATE INNER HANDLE	Serviceable	97.85 F	*- FL
37	1		*REAR WIPER MOTOR	Jammed	745.20 F	*745.20 FL
38	1		*REAR BUMPER	Bent	2,128.19 F	*675.00 FL
39	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	370.60 F	*185.30 FL
40	2		*REAR BUMPER CORNER PANEL GARNISH	Serviceable	493.50 F	*- FL
41	1		*REAR BUMPER GARNISH	Bent	325.40 F	*325.40 FL
42	1		*REAR BUMPER PARKING SENSOR GARNISH	Serviceable	164.90 F	*- FL
43	2		*REAR BUMPER REFLECTOR	Serviceable	441.90 F	*- FL
44	2		*REAR CORNER PANEL	Repair	530.60 F	*- FL
45	2		*REAR CORNER PANEL BRACKET	Repair	417.00 F	*- FL
46	1		*REAR END PANEL	Bent	1,589.60 F	*980.20 FL
47	1		*REAR END PANEL TOP GARNISH	Dented	375.60 F	*261.70 FL
48	1		*REAR FENDER INNER TRIM BOARD LH	Buckled	638.90 F	*638.90 FL
49	1		*REAR FENDER INNER TRIM BOARD RH	Buckled	638.90 F	*638.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR SPARE TYRE PANEL	Repair	1,023.60 F	*- FL
51	1		*REAR SPARE TYRES PANEL BOARD	Serviceable	756.30 F	*- FL
52	1		*REAR WEATHERSTRIP	Dented / Distorted	425.15 F	*346.50 FL
53	1		*REAR TAIL LAMP	O/S MtgCracked/N/S Serviceable	1,570.80 F	*785.40 FL
54	1		*REAR TAIL GATE LAMP	O/S MtgCracked/N/S Serviceable	1,306.40 F	*653.20 FL
55	1		*REAR TAIL GATE CAMERA	Serviceable	640.50 F	*- FL
56	1		*REAR ANTENNA SENSOR	Serviceable	389.10 F	*- FL
57	1		*INVERTER COOLER	Bent	654.30 F	*654.30 FL
58	1		*REAR EXHAUST	Repair	861.04 F	*- FL
59	6		*FRONT BONNET INSULATOR CLIP	Not Necessary	48.00 FS	*- FS
60	8		*FRONT BUMPER CLIP	Necessary	64.00 FS	*64.00 FS
61	1		*FRONT NUMBER PLATE }	Dented	30.00 FS	*45.00 FS
62	1		*FRONT NUMBER PLATE COVER }		30.00 FS	*- FS
63	1		*PARKING SENSOR (2PCS)	Cracked (1Pc Only)	440.00 FS	*220.00 FS
64	10		*REAR TRIM BOARD CLIP	Necessary	80.00 FS	*80.00 FS
65	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
66	6		*BUMPER CLIP	Necessary	48.00 FS	*48.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	38,970.86	18,906.88
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	4,602.47
Total Parts (\$)	38,970.86	14,304.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	New	2,500.00	1,400.00
2	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	New	1,500.00	1,200.00
3	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	New	300.00	40.00
4	TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	New	250.00	120.00
5	TO SUPPLY DIAGNOSTIC & REPROGRAMMING	New	300.00	0.00
6	TO SUPPLY LABOUR TO REMOVE & REFIT REAR WINDSCREEN	New	300.00	120.00
7	TO SUPPLY LABOUR TO REMOVE & REFIT REAR INNER UPHOLSTER	New	300.00	100.00
8	TO SUPPLY LABOUR TO TOP UP AIR COND GAS	New	120.00	100.00
Gross Labour Cost (S\$)			5,570.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >