



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 7325L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE ASSY (SN)	CRACKED	2,000.00	2,000.00
1	60KM STICKER (SN)	NECESSARY	20.00	10.00
1	REAR BUMPER (SN) (DENTED)	NOT CONSISTENT WITH THE IMPACT	1,600.00	-
1	REAR BUMPER REFLECTOR STICKER (SN)	NOT NECESSARY	150.00	-
2	TAIL GATE LOWER MEMBER STICKER @ 120.00 (SN)	NECESSARY	240.00	150.00
1	TAIL GATE BRACKET (SN)	BENT	160.00	80.00
			4,170.00	2,240.00
	<u>LABOUR</u>			
	TO RESPRAY AFFECTED AREAS.		900.00	200.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR, AND ALIGNED ALL PARTS.		900.00	400.00
			1,800.00	600.00
	GRAND TOTAL		5,970.00	2,840.00
RECOMMENDED COST OF REPAIR SUM				2,500.00

Report Ref No. CS/SMO24100066/Uqp3m4(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.