

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100077/AVP3E2
Date: 11/02/2025REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001245254
Claimant Vehicle No :	SKZ3598E	Insured Vehicle No :	SJM183T
Date of Loss:	08/09/2024	Nature of Claim:	TP
		Claim No:	372810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ3598E	Engine No:	K9KN837D213607
Make & Model:	RENAULT FLUENCE, 1.5 D (A)	Chassis No:	VF1LZLF0E53997589
Reg. Date:	20/01/2016 (Man. Year: 2015)	Odometer:	102604 km
Colour:	Black		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,843.25	2,846.23	3,997.02	58.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	910.00	1,240.00	57.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,993.25	3,756.23	5,237.02	58.23
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	8,993.25	3,000.00	5,993.25	66.64
+ GST 9.00/9.00% (S\$)	809.39	270.00	539.39	66.64
Nett Amount (S\$)	9,802.64	3,270.00	6,532.64	66.64

INSPECTION

Date of Assignment:	03/10/2024		
Date Inspected:	04/10/2024	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2025)
Parts:	143	RENAULT FLUENCE 1.5 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ3598E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,583.70 FL	*1,583.70 FL
2	1		*FRONT BUMPER SIDE HOLDER - RH	Not Necessary	46.80 FL	*- FL
3	1		*FRONT FENDER - RH	Dented	722.60 FL	*722.60 FL
4	1		*FRONT FENDER INNER SHIELD RH	Torn	178.40 FL	*178.40 FL
5	1		*HEAD LAMP - RH	Not Necessary	1,851.80 FL	*- FL
6	1		*FRONT LOWER ARM - RH	Not Necessary	445.80 FL	*- FL
7	1		*FRONT KNUCKLE ARM - RH	Not Necessary	569.40 FL	*- FL
8	1		*FRONT WHEEL HUB C/W BEARING - RH	Not Necessary	294.60 FL	*- FL
9	1		*FRONT SHOCK ABSORBER - RH	Not Necessary	399.40 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
11	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT WHEEL RIM	Cut	1,000.00 FS	*550.00 FS
13	1		*FRONT TYRE	Not Necessary	280.00 FS	*- FS
					F=Franchise part. S=SpcNett. L=ListItemDisc.	
					Sub Total (S\$)	7,452.50 3,094.70
					- List Item Discount on L Items 10.00/10.00% (S\$)	609.25 248.47
					Total Parts (S\$)	6,843.25 2,846.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT FRONT RH PORTION & RENEW ABOVE PARTS	New	800.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	800.00	400.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	0.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			2,150.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >