



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100080/Rvp3e2
16 RAFFLES QUAY	Date:	12/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6590H	Veh. Inspected	SLT 6990E
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008691MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	03/10/2024

### 2. Vehicle Details

Make & Model	MAZDA 5 2.0 AT S/R	C.C	1998
Engine No.	PE10524049	Year of Reg.	07/11/2017
Chassis No.	JM6CW1071H0126419	Colour	GREY
Odometer	72826 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55 R16	YOKOHAMA	6
L/H Front Tyre	205/55 R16	YOKOHAMA	6
R/H Rear Tyre	205/55 R16	YOKOHAMA	6
L/H Rear Tyre	205/55 R16	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	26/09/2024	Inspection Date	09/10/2024
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722		

5a. Remarks
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days