

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24100083/UVP3E2  
**Date:** 11/11/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003458453
<b>Claimant Vehicle No :</b>	SHD6370B	<b>Insured Vehicle No :</b>	XE2653S
Date of Loss:	02/10/2024	Nature of Claim:	TP
		Claim No:	375658

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD6370B</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR2F42008
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FUX03089377
Colour:	Maroon	Odometer:	419180 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodride 6 mm	Rear Left Side:	Goodride 6 mm
Front Right Side:	Goodride 6 mm	Rear Right Side:	Goodride 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,218.54	2,301.36	7,917.18	77.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,174.00	1,510.00	3,664.00	70.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,392.54</b>	<b>3,811.36</b>	<b>11,581.18</b>	<b>75.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,392.54</b>	<b>3,000.00</b>	<b>12,392.54</b>	<b>80.51</b>

**INSPECTION**

Date of Assignment:	04/10/2024	
Date Inspected:	04/10/2024	Inspected At: Strides Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2 Singapore 486443
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2024)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6370B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*PANEL SUB-ASSY, REAR DOOR, RH (DISC 30%)	Dented / Bent	1,401.70 F	*981.19 F
2	1	*PANEL SUB-ASSY, FENDER REAR RH (DISC 30%)	Cracked	943.10 F	*660.17 F
3	1	*STICKER LOGO (RR DOOR) (SN)	Necessary	60.00 F	*60.00 F
4	1	*WHEEL, DISC (SN)	Cut	2,036.30 F	*600.00 F
5	1	*TYRE	Serviceable	126.74 F	*- F
6	2	*PAD, RR BUMPER, RH & LH, 3	Not Necessary	24.00 F	*- F
7	2	*PAD, RR BUMPER, RH & LH, 2	Not Necessary	8.60 F	*- F
8	2	*PAD, RR BUMPER, RH & LH, 1	Not Necessary	8.60 F	*- F
9	1	*RETAINER, RR BUMPER, RH	Not Necessary	143.60 F	*- F
10	1	*CLIPS PIECE, RR BUMPER	Not Necessary	4.80 F	*- F
11	1	*PANEL SUB-ASSY, FRONT DOOR RH	Not Necessary	1,407.80 F	*- F
12	1	*STICKER LOGO (FRT DOOR)	Not Necessary	60.00 F	*- F
13	1	*MIRROR ASSY, OUTER REAR VIEW, RH	Not Necessary	1,556.00 F	*- F
14	1	*COVER, OUTER MIRROR, RH	Not Necessary	117.80 F	*- F
15	2	*PATCH, SIDE PANEL REAR END, RH & LH	Not Necessary	37.70 F	*- F
16	1	*LINER, REAR FENDER, RH	Not Necessary	151.10 F	*- F
17	2	*HUB & BEARING ASSY WITH SPEED SENSOR, REAR AXLE, RH & LH	Not Necessary	644.10 F	*- F
18	1	*COVER, RR BUMPER ASSY	Repair	525.40 F	*- F
19	1	*MOULDING ASSY, BODY ROCKER PANEL, RH	Repair	649.10 F	*- F
20	1	*MEMBER SUB-ASSY, RAIL BOOT SIDE REAR RH	Repair	312.10 F	*- F

F=Franchise part.

Total Parts (S\$) 10,218.54 2,301.36

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	1,352.00	600.00
2	SPRAY PAINT	New	2,392.00	750.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	40.00
6	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	60.00
7	TO REMOVE AND REFIT TYRE	New	120.00	0.00
8	TO TRANSFER DOOR MECHANISM	New	240.00	40.00
9	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
10	TO REMOVE AND REFIX UNDERCARRIAGE	New	350.00	0.00
11	TO REPLACE SUNDRY PARTS	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>5,174.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >