

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG24100084/ANP3E2**Date:** 28/02/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900002775
Claimant Vehicle No :	SMZ9621H	Insured Vehicle No :	SFN1133Z
Date of Loss:	25/09/2024	Nature of Claim:	TP
		Claim No:	6373044889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ9621H		
Make & Model:	BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)	Engine No:	30919552B37C15A
Reg. Date:	24/06/2016 (Man. Year: 2016)	Chassis No:	WBA2E320005B45034
Colour:	White	Odometer:	401861 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,828.51	4,560.03	8,268.48	64.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	580.00	1,450.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,858.51	5,140.03	9,718.48	65.41
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	14,858.51	4,100.00	10,758.51	72.41
+ GST 9.00/9.00% (S\$)	1,337.27	369.00	968.27	72.41
Nett Amount (S\$)	16,195.78	4,469.00	11,726.78	72.41

INSPECTION

Date of Assignment:	03/10/2024		
Date Inspected:	28/10/2024	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	902.30 FL	*902.30 FL
2	1		*FRONT BUMPER LOGO	Necessary	102.30 FL	*102.30 FL
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	48.50 FL	*- FL
4	2		*FRONT BUMPER FOGLAMP	Not Necessary	651.20 FL	*- FL
5	2		*FRONT BUMPER FOGLAMP COVER GARNISH	Not Necessary	431.80 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	191.85 FL	*191.85 FL
7	4		*FRONT BUMPER SENSOR	Not Necessary	1,424.80 FL	*- FL
8	4		*FRONT BUMPER SENSOR HOLDER	Not Necessary	188.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	796.00 FL	*- FL
10	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	105.00 FL	*- FL
11	2		*FRONT BUMPER TOP BEAM	Not Necessary	852.00 FL	*- FL
12	1		*FRONT BUMPER SPONGE	Cracked	294.00 FL	*294.00 FL
13	2		*FRONT BUMPER CORNER BRACKET	Not Necessary	148.00 FL	*- FL
14	1		*FRONT BUMPER LOWER BEAM	Not Necessary	195.00 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	197.00 FL	*- FL
16	1		*FRONT BUMPER ENGINE UNDER COVER	Not Necessary	441.00 FL	*- FL
17	1		*HEADLAMP (HID)	N/S Cracked	5,356.00 FL	*2,678.00 FL
18	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	100.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
20	1		*SET FRONT GRILLE (SPECIAL TYPE)	Cracked	850.00 FS	*550.00 FS
21	1		*SET FRONT GRILLE CLIP	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,444.75	4,768.45
- List Item Discount on L Items 5.00/5.00% (\$)	616.24	208.42
Total Parts (\$)	12,828.51	4,560.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	800.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	200.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE SETTLING	New	100.00	50.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
Gross Labour Cost (S\$)			2,030.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >