

ASS. REC. BY: Tajp

REF:

CS/FC124100085/Tv p3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JVM2290 Yr Regn: 2022, 07

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jamha 135LC c.c. 134Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMYUG/710N0020377Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NX / S/Rim / STD A/Rim orTyre Size: F: 80/90R17R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 03/10/24Survey held at First MotorDes. of Damages: Front / Rear / O/S / N/S / U/G / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1) _____

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Pop. Formet: _____

Lump Sum / I.B.I. (?) _____

First Motor

BLK 3006 UBI ROAD 1 #01-398 SINGAPORE 408700

TEL: 67431911 / 67448333 FAX NO: 67458131

RCB REG NO: 28964400C

EMAIL: first_motor_sg@yahoo.com

Date:

Ref no:

Veh No: JVM2290

Model: LC135

S/N	Description	Cost
1	MIRROR SET	50 ut
2	BRAKE LEVER	20 ut
3	HANDL BAR BALANCER	22 ut
4	HANDL BAR	75 ?
5	FOIL ASSY N UNDER BRACKET ASSY	380 bt
6	STEERING CON ASSY	80 ner
7	FRONT COVER COWLING	45 dis
8	REAR COVER COWLING	45 dis
9	RIGHT SIDE FEARING SET	110 mis
10	LEFT SIDE FEARING SET	110 mis
11	HEAD LAMP SET	48 ut
12	WHEEL FRONT	210 ?
13	DIS ROTOR	110 ?
14	WHEEL SHAFT + Nut	22 ?
15	RADIATOR ASSY	350 bt
16	LOWER COWLING ASSY	60 dis
17	METER COVER ASSY	45 mis
18	FOOT REST BAR	30 dis
19	FOOT BRAKE PADDLE	28 bt

First Motor

BLK 3006 UBI ROAD 1 #01-398 SINGAPORE 408700

TEL: 67431911 / 67448333 FAX NO: 67458131

RCB REG NO: 28964400C

EMAIL: first_motor_sg@yahoo.com

Date:

Ref no:

Veh No: JYM 2290

Model: LC 135

S/N	Description	Cost
20	EXHAUST PIPE GUARD 3pc.	90 cat
21	BASKET.	40 cat
22	CHASSIS REPAIR	380 2 pth 200
23	Front tyre 70/80/17	70 cat ✓
5		
6		
7		
8		
9		
10		
	Total parts & repair	2350
	Total	
	Labour & Misc.	200
	Labour Charge	300
	Towing From Accident Compound	70 ✓
	Transport Fee	
	Grand Total	2720

LKK Auto Centre

the Repairer of the form

- To return to the repairer
- To display damaged parts during resurvey
- Parts price to be submitted for confirmation
- Third party survey in a "Without Franchise" manner
- No illegal modification is allowed
- Supplementary work is subject to final approval by insurance company

Authorised signature

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749 / 62563561

3/10/24 2:51pm

Resurvey new items

Tan Jiah e lkhant.com

3 days.