



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: AINI		Ref: CS/FCI24100085/Tvp3e2(N) Date: 04/10/2024 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9714Y	Veh. Inspected	JVM 2290
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24007462MFCT	Excess (\$)	0.00
Assign From	AINI	Assign Date	03/10/2024
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA 135LC	c.c	134
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	PMYUG1710N0020377	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90 R17	MAXXIS	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90 R17	MAXXIS	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/08/2024	Inspection Date	03/10/2024
Survey held at	FIRST MOTOR BLK 3006 UBI RD 1 #01-398 SINGAPORE 408700		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	