

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24060198/AVH3M4

Date: 26/08/2024

REFERENCE

|                       |                                       |                      |                  |
|-----------------------|---------------------------------------|----------------------|------------------|
| Handling Insurer:     | India International Insurance Pte Ltd | Policy No:           | D20MFL0007747_03 |
| Claimant Vehicle No : | SNM2128T                              | Insured Vehicle No : | SMZ435M          |
| Date of Loss:         | 21/06/2024                            | Nature of Claim:     | TP               |
|                       |                                       | Claim No:            | N/A              |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                          |             |                   |
|-----------------------------|------------------------------------------|-------------|-------------------|
| Reg No:                     | SNM2128T                                 | Engine No:  | P520914424        |
| Make & Model:               | MAZDA 3, 1.5 4DR M-HYBRID CLASSIC I2 (A) | Chassis No: | JM6BP2SAAP1153540 |
| Reg. Date:                  | 31/08/2023 (Man. Year: 2023)             | Odometer:   | 77478 km          |
| Colour:                     | White                                    |             |                   |
| Engine Capacity:            | 1496 cc                                  |             |                   |
| Market Value/New Car Price: | N/A                                      |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price               |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/60R16     | Rear Tyre Size:  | 205/60R16     |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 9,800.40   | 4,353.60   | 5,446.80   | 55.58  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 3,530.00   | 1,800.00   | 1,730.00   | 49.01  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 13,330.40  | 6,153.60   | 7,176.80   | 53.84  |
| Approved Total (Overridden) (S\$) |            | 4,900.00   |            |        |
| Nett Amount (S\$)                 | 13,330.40  | 4,900.00   | 8,430.40   | 63.24  |

INSPECTION

|                             |            |               |                                                                                          |
|-----------------------------|------------|---------------|------------------------------------------------------------------------------------------|
| Date of Assignment:         | 24/06/2024 |               |                                                                                          |
| Date Inspected:             | 25/06/2024 | Inspected At: | AUTOMOBILE HUB ENTERPRISE<br>1 KAKI BUKIT AVENUE 6<br>#01-15 AUTOBAY<br>SINGAPORE 417883 |
| Estimated Period of Repair: | 6.0 days   |               |                                                                                          |

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                           |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                           |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 26 Aug 2024)                             |
| Parts:        | 143                                                                                                                                                                          | MAZDA 3 1.5 4DR M-HYBRID CLASSIC I2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                         |
| Print Code:   | (Unsubmitted, no print-code for SNM2128T)                                                                                                                                    |                                                                           |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                           |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                           |

Recommended Parts

| No.                                           | Qty | Part No. | Particulars                              | Condition          | Repairer's  | Amount     |
|-----------------------------------------------|-----|----------|------------------------------------------|--------------------|-------------|------------|
| 1                                             | 1   |          | *REAR BUMPER                             | Distorted          | 977.00 FL   | *977.00 FL |
| 2                                             | 1   |          | *REAR BUMPER CENTRE BRACKET              | Not Necessary      | 40.00 FL    | *- FL      |
| 3                                             | 1   |          | *REAR BUMPER END SEAL COVER              | Deformed           | 68.00 FL    | *68.00 FL  |
| 4                                             | 1   |          | *REAR BUMPER INNER SIDE BRACKET          | Not Necessary      | 41.00 FL    | *- FL      |
| 5                                             | 1   |          | *REAR BUMPER LOWER BRACKET               | Not Necessary      | 105.00 FL   | *- FL      |
| 6                                             | 1   |          | *REAR BUMPER LOWER INNER BRACKET         | Cracked            | 93.00 FL    | *93.00 FL  |
| 7                                             | 2   |          | *REAR BUMPER REFLECTOR                   | Cracked            | 98.00 FL    | *98.00 FL  |
| 8                                             | 1   |          | *REAR BUMPER REINFORCEMENT               | Dented             | 547.00 FL   | *547.00 FL |
| 9                                             | 1   |          | *REAR BUMPER REVERSE SENSOR              | Damaged (1Pc Only) | 380.00 FL   | *190.00 FL |
|                                               |     | 2PCS     |                                          |                    |             |            |
| 10                                            | 4   |          | *REAR BUMPER REVERSE SENSOR HOLDER       | Not Necessary      | 184.00 FL   | *- FL      |
| 11                                            | 1   |          | *REAR BUMPER REVERSE SENSOR WIRE HARNESS | Not Necessary      | 508.00 FL   | *- FL      |
| 12                                            | 2   |          | *REAR BUMPER SCREW HOLDER                | Not Necessary      | 84.00 FL    | *- FL      |
| 13                                            | 2   |          | *REAR BUMPER SIDE BRACKET                | Not Necessary      | 76.00 FL    | *- FL      |
| 14                                            | 4   |          | *REAR BUMPER SIDE BRACKET RIVET          | Not Necessary      | 24.00 FL    | *- FL      |
| 15                                            | 1   |          | *REAR BUMPER SIDE HOLDER                 | Cracked            | 69.00 FL    | *69.00 FL  |
| 16                                            | 1   |          | *REAR BUMPER TOW COVER                   | Not Necessary      | 35.00 FL    | *- FL      |
| 17                                            | 1   |          | *REAR BUMPER UNDERCOVER                  | Torn               | 99.00 FL    | *99.00 FL  |
| 18                                            | 1   |          | *REAR BUMPER CHASSIS MEMBER TOP PANEL    | Not Necessary      | 296.00 FL   | *- FL      |
| 19                                            | 1   |          | *REAR END PANEL                          | Dented             | 691.00 FL   | *691.00 FL |
| 20                                            | 1   |          | *REAR END PANEL TOP GARNISH              | Not Necessary      | 105.00 FL   | *- FL      |
| 21                                            | 1   |          | *REAR END PANEL ANTENNA SENSOR           | Not Necessary      | 98.00 FL    | *- FL      |
| 22                                            | 1   |          | *TAILLAMP                                | Cracked            | 903.00 FL   | *903.00 FL |
| 23                                            | 1   |          | *TAILLAMP PANEL                          | Repair             | 375.00 FL   | *- FL      |
| 24                                            | 1   |          | *REAR FENDER                             | Repair             | 1,643.00 FL | *- FL      |
| 25                                            | 1   |          | *REAR FENDER INNER TRIM COVER            | Deformed           | 769.00 FL   | *769.00 FL |
| 26                                            | 1   |          | *REAR FEDNER INNER SHIELD                | Not Necessary      | 139.00 FL   | *- FL      |
| 27                                            | 1   |          | *REAR FENDER AIR VENT                    | Deformed           | 88.00 FL    | *88.00 FL  |
| 28                                            | 1   |          | *REAR FENDER AIR VENT PANEL              | Dented             | 148.00 FL   | *148.00 FL |
| 29                                            | 1   |          | *REAR WINDSCREEN MOULDING                | Not Necessary      | 109.00 FL   | *- FL      |
| 30                                            | 1   |          | *SPARE TYRE PANEL SIDE SPONGE            | Cracked            | 245.00 FL   | *245.00 FL |
| 31                                            | 1   |          | *SPARE TYRE PANEL TOP COVER              | Not Necessary      | 671.00 FL   | *- FL      |
| 32                                            | 1   |          | *SPARE TYRE SIDE PANEL                   | Not Necessary      | 169.00 FL   | *- FL      |
| 33                                            | 1   |          | *REAR HORN                               | Not Necessary      | 99.00 FL    | *- FL      |
| 34                                            | 1   |          | *REAR HORN BRACKET                       | Not Necessary      | 28.00 FL    | *- FL      |
| 35                                            | 1   |          | *REAR EXHAUST PIPE                       | Not Necessary      | 1,299.00 FL | *- FL      |
| 36                                            | 1   |          | *REAR EXHAUST PIPE MOUNTING              | Not Necessary      | 39.00 FL    | *- FL      |
| 37                                            | 1   |          | *REAR EXHAUST PIPE GASKET                | Not Necessary      | 35.00 FL    | *- FL      |
| 38                                            | 1   |          | *REAR EXHAUST PIPE HEAT SHIELD           | Not Necessary      | 129.00 FL   | *- FL      |
| 39                                            | 1   |          | *SPARE TYRE PANEL SIDE TRAY              | Deformed           | 282.00 FL   | *282.00 FL |
| 40                                            | 1   |          | *SET REAR BUMPER CLIPS                   | Necessary          | 30.00 FS    | *30.00 FS  |
| 41                                            | 1   |          | *SET REAR BUMPER UNDERCOVER CLIPS        | Necessary          | 20.00 FS    | *20.00 FS  |
| 42                                            | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS    | Not Necessary      | 20.00 FS    | *- FS      |
| 43                                            | 1   |          | *SET REAR END PANEL SEALANT              | Necessary          | 60.00 FS    | *60.00 FS  |
| 44                                            | 1   |          | *REAR FENDER SEALANT                     | Not Necessary      | 60.00 FS    | *- FS      |
| 45                                            | 1   |          | *SET REAR FENDER INNER TRIM CLIPS        | Necessary          | 30.00 FS    | *30.00 FS  |
| Report was unsubmitted during this print-out. |     |          |                                          |                    |             |            |

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|--------|
| 46  | 1   |          | *SET REAR FENDER INNER SHIELD CLIPS | Not Necessary | 30.00 FS   | *- FS  |
| 47  | 1   |          | *SET REAR WINDSCREEN SEALANT        | Not Necessary | 60.00 FS   | *- FS  |
| 48  | 1   |          | *SPARE TYRE PANEL SEALANT           | Not Necessary | 60.00 FS   | *- FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                   |           |          |
|---------------------------------------------------|-----------|----------|
| Sub Total (\$)                                    | 12,158.00 | 5,407.00 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 2,357.60  | 1,053.40 |
| Total Parts (\$)                                  | 9,800.40  | 4,353.60 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                           | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                       |          |                 |                 |
| 1                               | PANEL BEATING, REMOVE AND REFIT PARTS | New      | 1,400.00        | 800.00          |
| 2                               | SPRAY PAINTING TO AFFECTED AREA       | New      | 1,200.00        | 800.00          |
| 3                               | WIRING CHECK                          | New      | 50.00           | 30.00           |
| 4                               | TO APPLY TUFF COAT                    | New      | 150.00          | 60.00           |
| 5                               | TO REMOVE REVERSE SENSOR              | New      | 100.00          | 50.00           |
| 6                               | TO REMOVE UPHOLSTERY                  | New      | 150.00          | 60.00           |
| 7                               | TO REMOVE REAR WINDSCREEN             | New      | 180.00          | 0.00            |
| 8                               | TO REMOVE EXHAUST PIPE                | New      | 150.00          | 0.00            |
| 9                               | TO REMOVE FUEL TANK                   | New      | 150.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                       |          | <b>3,530.00</b> | <b>1,800.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >