



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100087/Avp3m4
75 BRAS BASAH ROAD	Date:	11/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCA 8888L	Veh. Inspected	SLH 4279C
Policy No.	-	Coverage	0
Claim No.	MT/1297862-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	03/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA COROLLA AXIO	C.C	1496
Engine No.	1NZR426579	Year of Reg.	02/11/2016
Chassis No.	NKE1657136810	Colour	BEIGE
Odometer	179664 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/50R16	BRIDGESTONE	6
L/H Front Tyre	195/50R16	BRIDGESTONE	6
R/H Rear Tyre	195/50R16	BRIDGESTONE	6
L/H Rear Tyre	195/50R16	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	30/09/2024	Inspection Date	25/10/2024 (13:56)
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days