



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2503821

16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581  
ATTN:ZENA LIM

INV Date 18/06/2025  
Reference CD/FCI24100089/Ema3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SMX 3899Z  
Insured Veh. SHB 6166K  
Claim No. D24008727MFCT/CTPL  
Policy No. D-24101861MFCT  
Accident Date 02/10/2024  
Inspection Date 07/10/2024

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 500.00        |
| <b>Subtotal</b>                | <b>500.00</b> |
| <b>GST (9%)</b>                | <b>45.00</b>  |
| <b>Grand Total</b>             | <b>545.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|                                   |       |                       |
|-----------------------------------|-------|-----------------------|
| MS MS FIRST CAPITAL INSURANCE LTD | Ref:  | CD/FCI24100089/Ema3q2 |
| 16 RAFFLES QUAY                   | Date: | 18/06/2025            |
| #42-01 HONG LEONG BUILDING        | Code: | FCI2                  |
| SINGAPORE 048581                  |       |                       |

### 1. Policy Particulars :- DIRECT SETTLEMENT

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHB 6166K      | Veh. Inspected | SMX 3899Z  |
| Policy No.   | D-24101861MFCT | Coverage       | 0          |
| Claim No.    | C              | Excess         | \$0.00     |
| Assign From  | JOANNE YONG    | Assign Date    | 04/10/2024 |

### 2. Vehicle Details

|                 |                         |              |            |
|-----------------|-------------------------|--------------|------------|
| Make & Model    | HONDA CIVIC 1.6 VTI CVT | C.C          | 1597       |
| Engine No.      | R16B25520549            | Year of Reg. | 11/01/2021 |
| Chassis No.     | MRHFC5650LT000433       | Colour       | BLACK      |
| Odometer        | 85493 KM                | Steering     | IN ORDER   |
| Brakes          | IN ORDER                | General      | GOOD       |
| Modification(s) | RIMS: SPORTS RIM        |              |            |

### 3. Conditions of Tyres

|                | Size        | Make   | Balance (mm) |
|----------------|-------------|--------|--------------|
| R/H Front Tyre | 245/45Z R17 | PATLAS | 5            |
| L/H Front Tyre | 245/45Z R17 | PATLAS | 5            |
| R/H Rear Tyre  | 245/45Z R17 | PATLAS | 5            |
| L/H Rear Tyre  | 245/45Z R17 | PATLAS | 5            |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                              |                 |            |
|----------------|--------------------------------------------------------------|-----------------|------------|
| Accident Date  | 02/10/2024                                                   | Inspection Date | 07/10/2024 |
| Survey held at | KAH MOTOR.CO.SDN.BHD<br>6A MANDAI ESTATE<br>SINGAPORE 729903 |                 |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMX 3899Z

| Special Nett |                                    |               |                        |                   |
|--------------|------------------------------------|---------------|------------------------|-------------------|
| Qty          | Description of Parts               | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1            | PANEL COMPL FR DOOR (SN)           | DENTED        | \$711.90               | \$711.90          |
| 1            | HINGE L FR DOOR UPPER (SN)         | NOT NECESSARY | \$34.80                | \$0.00            |
| 1            | HINGEL FR DOOR LOWER (SN)          | NOT NECESSARY | \$35.62                | \$0.00            |
| 1            | CHECKER COMPFR DOOR (SN)           | NOT NECESSARY | \$12.30                | \$0.00            |
| 1            | SEALL ,FR DOOR FR GAP (SN)         | BENT          | \$11.32                | \$11.32           |
| 1            | SEALL,FR DOOR LOWER (SN)           | NECESSARY     | \$7.42                 | \$7.42            |
| 1            | MOLDING ASSYL,FR DOOR SASH (SN)    | NECESSARY     | \$24.07                | \$24.07           |
| 1            | GARNISHL FR CENTER CORNER (SN)     | NECESSARY     | \$1.42                 | \$1.42            |
| 1            | GARNISH ASSYL FR DOOR SASH (SN)    | NECESSARY     | \$12.37                | \$12.37           |
| 1            | MOLDING ASSYL FR DOOR (SN)         | NECESSARY     | \$21.82                | \$21.82           |
| 1            | LATCH ASSYL FR DOOR POWER (SN)     | NOT NECESSARY | \$83.62                | \$0.00            |
| 1            | REGULATOR ASSYL FR DOOR (SN)       | NOT NECESSARY | \$81.97                | \$0.00            |
| 1            | PANELL RR DOOR (SN)                | DENTED        | \$651.22               | \$651.22          |
| 1            | HINGEL R DOOR UPPER (SN)           | NOT NECESSARY | \$34.50                | \$0.00            |
| 1            | HINGEL RR DOOR LOWER (SN)          | NOT NECESSARY | \$34.80                | \$0.00            |
| 1            | CHECKER COMPRR DOOR (SN)           | NOT NECESSARY | \$8.55                 | \$0.00            |
| 1            | SEALRR DOOR LOWER (SN)             | NECESSARY     | \$5.55                 | \$5.55            |
| 1            | MOLDING ASSY ,RR DR INNER (SN)     | NECESSARY     | \$46.50                | \$46.50           |
| 1            | GARNISH ASSYL RR DOOR SASH (SN)    | NECESSARY     | \$21.22                | \$21.22           |
| 1            | GARNISHL RR DOOR QUARTER OUT (SN)  | NECESSARY     | \$17.62                | \$17.62           |
| 1            | GARNISHL RR CENTER CORNER (SN)     | NOT NECESSARY | \$1.20                 | \$0.00            |
| 1            | MOLDING ASSYL RR DOOR (SN)         | NECESSARY     | \$22.87                | \$22.87           |
| 1            | LATCH ASSYL RR DOOR POWER (SN)     | NOT NECESSARY | \$145.87               | \$0.00            |
| 1            | REGULATOR ASSYL RR DOOR POWER (SN) | NOT NECESSARY | \$99.75                | \$0.00            |
| 1            | GARNISH ASSY,L SIDE SILL (SN)      | BROKEN        | \$106.87               | \$106.87          |
| 1            | PANEL SET L RR OUTSIDE (SN)        | DENTED        | \$1,015.42             | \$1,015.42        |
| 1            | FENDER L.RR. INNER (SN)            | NOT NECESSARY | \$77.10                | \$0.00            |
| 8            | CLIPINNER FENDER (SN)              | NECESSARY     | \$14.40                | \$14.40           |
| 1            | RUBBER CWINDOWSHIELD DAM (SN)      | NECESSARY     | \$15.67                | \$15.67           |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

| Special Nett |                                                     |           |                        |                   |
|--------------|-----------------------------------------------------|-----------|------------------------|-------------------|
| Qty          | Description of Parts                                | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 3            | RUBBERRRR QTR W/SHIELD (SN)                         | NECESSARY | \$23.85                | \$23.85           |
| 2            | FASTENER BW/SHIELD (SN)                             | NECESSARY | \$7.95                 | \$7.95            |
| 2            | FASTENER AW/SHIELD (SN)                             | NECESSARY | \$5.70                 | \$5.70            |
| 2            | CLIP WINDSHIELD UPPER (SN)                          | NECESSARY | \$5.40                 | \$5.40            |
| 1            | RUBBER W/SHIELD (SN)                                | NECESSARY | \$10.87                | \$10.87           |
| 1            | RUBBER W/SHIELD (SN)                                | NECESSARY | \$12.37                | \$12.37           |
| 2            | WINDSCREEN SEALANT (SN)                             | NECESSARY | \$120.00               | \$120.00          |
| 1            | 17 INCH GROSS BLACK FULL POLISH CIVIC RIM SC22 (SN) | CUT       | \$320.00               | \$320.00          |
| 1            | SUNDRIES (SN)                                       | NECESSARY | \$100.00               | \$50.00           |
| 1            | GLASS ASSY ,L QUARTER WINDSHIELD (SN) (ADDITIONAL)  | NECESSARY | \$123.90               | \$123.90          |
|              |                                                     |           | \$4,087.78             | \$3,387.70        |

| Labour |                                                            |           |                        |                   |
|--------|------------------------------------------------------------|-----------|------------------------|-------------------|
|        | Description of Parts                                       | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
|        | REPLACE RR R QTR GLASS . (ADDITIONAL)                      |           | \$450.00               | \$450.00          |
|        | SUPPLY & INSTALL SOLAR FILM ON REAR QTR GLASS (ADDITIONAL) |           | \$280.00               | \$280.00          |
|        | REPLACE RR WINDSCREEN (                                    |           | \$650.00               | \$650.00          |
|        | INSPECT RR LIGHTING MECHANISMS PERFORM WATER               |           | \$280.00               | \$250.00          |
|        | TRANSFER FR L DOOR INCLUDING FITTINGS ON                   |           | \$650.00               | \$650.00          |
|        | TRANSFER RR L DOOR INCLUDING FITTINGS                      |           | \$650.00               | \$650.00          |
|        | RESET VEHICLE SMART ENTRY SYSTEM                           |           | \$650.00               | \$600.00          |
|        | REMOVE & INSTALL ROOF LINING GARNISHES SEATS               |           | \$650.00               | \$650.00          |
|        | REMOVE & INSTALL FUEL TANK FUEL PIPES                      |           | \$550.00               | \$500.00          |
|        | REMOVE & RENEW RR L RIM INCLUDE BALANCING                  |           | \$80.00                | \$80.00           |
|        | BODY JOINT SEALANT RR FENDER                               |           | \$80.00                | \$80.00           |
|        | WINDSCREEN DAM KIT                                         |           | \$100.00               | \$100.00          |
|        | CUT & RENEW RR L FENDER STRAIGHTEN INNER PANEL             |           | \$6,500.00             | \$3,250.00        |
|        | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS               |           | \$3,640.00             | \$2,600.00        |
|        | WHEEL ALIGNMENT                                            |           | \$220.00               | \$220.00          |
|        |                                                            |           | \$15,430.00            | \$11,010.00       |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

|                                      |                             |             |             |
|--------------------------------------|-----------------------------|-------------|-------------|
| GRAND TOTAL                          |                             | \$19,517.78 | \$14,397.70 |
|                                      | RECOMMENDED COST OF REPAIRS |             | \$14,397.70 |
| Report Ref No: CD/FCI24100089/Ema3q2 |                             |             |             |

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 20)

### PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 20 of 20)

### PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMX 3899Z**

