

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100090/APA3Q2
Date: 17/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372_03
Claimant Vehicle No : SKE6780K Insured Vehicle No : SHD2604D
Date of Loss: 03/10/2024 Nature of Claim: TP Claim No: MFL2024D0011711

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE6780K
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX529603
Reg. Date: 18/09/2015 (Man. Year: 2015) Chassis No: MR053REH104538523
Colour: Blue Odometer: 276279 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,536.72	5,945.47	13,591.25	69.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,000.00	3,160.00	3,840.00	54.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,536.72	9,105.47	17,431.25	65.69
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	26,536.72	7,000.00	19,536.72	73.62
+ GST 9.00/9.00% (S\$)	2,388.30	630.00	1,758.30	73.62
Nett Amount (S\$)	28,925.02	7,630.00	21,295.02	73.62
+ Loss of Use (14.0 x S\$60.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		8,528.25		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment: 04/10/2024
Date Inspected: 04/10/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2025)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE6780K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	756.10 FL	*- FL
2	1		*BOOTLID LAMP LH	Cut	342.00 FL	*342.00 FL
3	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
4	1		*BOOTLID EMBLEM COROLLA	Necessary	70.00 FL	*70.00 FL
5	1		*BOOTLID EMBLEM ALTIS	Necessary	70.00 FL	*70.00 FL
6	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
7	1		*BOOTLID TOP LOCK	Not Necessary	318.10 FL	*- FL
8	1		*BOOTLID LOWER LOCK	Not Necessary	20.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Necessary	195.00 FL	*- FL
10	1		*TAILLAMP	N/S Cracked	930.00 FL	*465.00 FL
11	1		*TAILLAMP LOWER BRACKET	N/S Cracked	230.20 FL	*65.00 FL
12	1		*TAILLAMP PANEL LH	Dented	198.00 FL	*198.00 FL
13	1		*REAR DOOR LH	Dented	1,250.00 FL	*1,250.00 FL
14	1		*REAR DOOR LOCK CATCHER LH	Not Necessary	60.00 FL	*- FL
15	1		*REAR DOOR INNER LOCK LH	Damaged	480.00 FL	*480.00 FL
16	1		*REAR DOOR INNER TRIM LH	Not Necessary	890.00 FL	*- FL
17	1		*REAR DOOR WEATHERSTRIP LH	Cut	175.00 FL	*175.00 FL
18	1		*REAR DOOR FRAME WEATHERSTRIP LH	Not Necessary	110.00 FL	*- FL
19	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	160.00 FL	*- FL
20	1		*REAR FENDER LH	Distorted	987.00 FL	*987.00 FL
21	1		*REAR FENDER INNER PANEL LH	Repair	876.00 FL	*- FL
22	2		*REAR FENDER INNER COWLING	Not Necessary	700.40 FL	*- FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	1,540.20 FL	*- FL
24	1		*REAR FENDER AIR VENT LH	Deformed	75.00 FL	*75.00 FL
25	1		*REAR WHEEL HOUSE PANEL LH	Buckled	897.40 FL	*897.40 FL
26	1		*REAR WHEEL HOUSE PANEL SUPPORT PANEL LH	Repair	480.00 FL	*- FL
27	1		*REAR FUEL TANK INLET PIPE	Not Necessary	193.20 FL	*- FL
28	1		*REAR FUEL TANK PIPE COVER HOLDER	Not Necessary	68.50 FL	*- FL
29	1		*REAR FUEL TANK PIPE DOOR PANEL	Repair	156.40 FL	*- FL
30	1		*REAR FUEL TANK PIPE DOOR PANEL LOCK	Not Necessary	96.30 FL	*- FL
31	1		*REAR FUEL TANK PIPE DOOR PANEL LOCK CABLE	Not Necessary	176.20 FL	*- FL
32	1		*REAR FUEL TANK INLET PIPE COVER GARNISH	Not Necessary	68.50 FL	*- FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	163.00 FL	*163.00 FL
34	1		*REAR WHEEL RIM LH	Cut	738.75 FS	*500.00 FS
35	1		*REAR ABS SENSOR LH	Not Necessary	295.00 FL	*- FL
36	1		*REAR WHEEL HUP C/W BEARING LH	Not Necessary	810.00 FL	*- FL
37	1		*REAR SHOCK ABSORBER LH	Not Necessary	390.00 FL	*- FL
38	1		*REAR AXLE	Not Necessary	2,850.00 FL	*- FL
39	1		*REAR END PANEL	Dented	695.30 FL	*695.30 FL
40	1		*REAR END PANEL TOP GARNISH	Not Necessary	250.10 FL	*- FL
41	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	271.10 FL	*- FL
42	1		*REAR FLOOR PANEL	Repair	940.20 FL	*- FL
43	1		*REAR FLOOR SIDE PANEL LH	Dented	294.60 FL	*294.60 FL
44	1		*REAR BUMPER	Distorted	539.90 FL	*539.90 FL
45	1		*REAR BUMPER REINFORCEMENT	Not Necessary	386.60 FL	*- FL
46	1		*REAR BUMPER REFLECTOR	N/S Cracked	150.20 FL	*75.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REVERSE SENSOR	Not Necessary	386.20 FL	*- FL
48	2		*REAR CHASSIS EXTEND MEMBER	Not Necessary	1,300.60 FL	*- FL
49	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
51	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
52	1		*TAILLAMP PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
53	1		*REAR FENDER SEALANT	Necessary	150.00 FS	*60.00 FS
54	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
55	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
56	1		*REAR WHEEL HOUSE PANEL SEALANT	Not Necessary	180.00 FS	*- FS
57	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
58	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
59	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
61	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
62	1		*REAR DOOR SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*REAR TYRE LH	Not Necessary	350.00 FS	*- FS
64	1		*BRAKE OIL	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,166.05	7,677.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,629.33	1,731.83
Total Parts (\$\$)	19,536.72	5,945.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,200.00	1,400.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	0.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	TRANSFER REAR DOOR MECHANISM	New	180.00	60.00
12	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
13	REMOVE AND REFIX FUEL TANK TO FACILITATE REAR FENDER REPLACEMENT	New	80.00	60.00
14	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	80.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			7,000.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >