

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100092/AMA3Q2**Date:** 10/11/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800143689
Claimant Vehicle No : GBK5315C **Insured Vehicle No :** SGP9298G
 Date of Loss: 17/09/2024 Nature of Claim: TP Claim No: 8077636026SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK5315C**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 4DR (A) Engine No: 1KDB046914
 Reg. Date: 28/08/2020 (Man. Year: 2020) Chassis No: JTFHT02P000250687
 Colour: Silver Odometer: 156784 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,200.00	600.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,800.00	1,200.00	600.00	33.33
+ GST 9.00/9.00% (S\$)	162.00	108.00	54.00	33.33
Nett Amount (S\$)	1,962.00	1,308.00	654.00	33.33
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,490.18		
Global Sum Settlement (S\$)		1,490.00		

INSPECTION

Date of Assignment: 02/10/2024
 Date Inspected: 02/10/2024 Inspected At: Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
 Singapore 417921
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR AND RESPRAY PAINTING ON FRT BUMPER ,FRT DOOR LH ,SIDE SLIDING DOOR ,REAR FENDER LH AND REAR BUMPER	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			1,800.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >