

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100094/AUA3Q2**Date:** 07/07/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230111823
Claimant Vehicle No :	SJM2756C	Insured Vehicle No :	SMA5742A
Date of Loss:	01/10/2024	Nature of Claim:	TP
		Claim No:	5100366114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2756C	Engine No:	1NZX831353
Make & Model:	TOYOTA VIOS, 1.5 J (A)	Chassis No:	MR053HY9305089735
Reg. Date:	26/12/2008 (Man. Year: 2008)	Odometer:	160345 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,902.65	3,112.70	1,789.95	36.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	2,360.00	710.00	23.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,972.65	5,472.70	2,499.95	31.36
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	7,972.65	4,400.00	3,572.65	44.81
+ GST 9.00/9.00% (S\$)	717.54	396.00	321.54	44.81
Nett Amount (S\$)	8,690.19	4,796.00	3,894.19	44.81
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		5,696.00		
Global Sum Settlement (S\$)		5,690.00		

INSPECTION

Date of Assignment:	02/10/2024		
Date Inspected:	02/10/2024	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	766.70 FL	*766.70 FL
2	1		*BOOTLID LOCK	Damaged	139.00 FL	*139.00 FL
3	1		*BOOTLID W/STRIP	Cut	200.00 FL	*200.00 FL
4	1		*LOGO EMBLEM	Necessary	72.20 FL	*72.20 FL
5	1		*VIOS EMBLEM	Necessary	48.00 FL	*48.00 FL
6	1		*BOOTLID OUTER GARNISH	Not Necessary	270.00 FL	*- FL
7	2		*TAILLAMP	Cracked	620.00 FL	*620.00 FL
8	2		*TAILLAMP SEAL	Necessary	56.00 FL	*56.00 FL
9	2		*TAILLAMP CLIPS	Not Necessary	21.60 FL	*- FL
10	1		*REAR BUMPER	Deformed	595.70 FL	*595.70 FL
11	2		*REAR BUMPER RETAINER LONG	Not Necessary	200.00 FL	*- FL
12	2		*REAR BUMPER RETAINER SHORT	Not Necessary	120.00 FL	*- FL
13	1		*REAR BUMPER REFLECTORS	O/S Cracked	250.00 FL	*125.00 FL
14	2		*REAR BUMPER BRACKET	Not Necessary	140.00 FL	*- FL
15	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
16	1		*END PANEL	Dented	745.00 FL	*745.00 FL
17	1		*END PANEL INNER GARNISH	Deformed	235.00 FL	*235.00 FL
18	1		*SPARE TYRE PANEL	Repair	755.00 FL	*- FL
19	1		*SPARE TYRE CARDBOARD CENTRE	Cracked	145.00 FL	*145.00 FL
20	2		*SPARE TYRE CARDBOARD LH RH	Deformed	106.00 FL	*106.00 FL
21	1		*EXHAUST PIPE	Repair	635.00 FL	*- FL
22	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
23	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,440.20	4,083.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,537.55	970.90
Total Parts (\$\$)	4,902.65	3,112.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	1,100.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	RUST PROOFING	New	80.00	60.00
4	UPHOLSTERY	New	120.00	60.00
5	WIRING	New	30.00	30.00
6	REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
7	REMOVE & REFIT EXHAUST PIPE	New	120.00	60.00
Gross Labour Cost (\$\$)			3,070.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >