

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100095/AUA3Q2**Date:** 27/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070851
Claimant Vehicle No : SLE316X **Insured Vehicle No :** SLT3862L
 Date of Loss: 27/09/2024 Nature of Claim: TP Claim No: 9374699757SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE316X**
 Make & Model: HONDA VEZEL, 1.5 X HYBRID AT ABS D/AIRBAG 2WD (A) Engine No: LEB5069549
 Reg. Date: 04/07/2016 (Man. Year: 2016) Chassis No: RU31119533
 Colour: Grey Odometer: 546023 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,356.04	19,029.68	31,326.36	62.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,450.00	5,080.00	6,370.00	55.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,806.04	24,109.68	37,696.36	60.99
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	61,806.04	17,000.00	44,806.04	72.49
+ GST 9.00/9.00% (S\$)	5,562.54	1,530.00	4,032.54	72.49
Nett Amount (S\$)	67,368.58	18,530.00	48,838.58	72.49
+ Car Rental (5.0 x S\$80.00/day + 9.00% GST) (S\$)		436.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		19,053.25		
Global Sum Settlement (S\$)		19,050.00		

INSPECTION

Date of Assignment: 30/09/2024
 Date Inspected: 30/09/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	927.50 FL	*765.00 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	27.40 FL	*- FL
3	1		*FRONT BUMPER LOWER LIP	Deformed	351.00 FL	*351.00 FL
4	2		*FRONT BUMPER FOG LAMP	Not Necessary	655.40 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP COVER	Torn	98.00 FL	*98.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Torn	189.00 FL	*189.00 FL
7	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	46.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	356.00 FL	*356.00 FL
9	1		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Not Necessary	86.55 FL	*- FL
10	2		*ENGINE SIDE COVER GARNISH	Not Necessary	130.80 FL	*- FL
11	1		*ENGINE UNDER COVER	Not Necessary	589.10 FL	*- FL
12	2		*FRONT FENDER	Repair	1,160.00 FL	*- FL
13	2		*FRONT FENDER INNER COWLING	Not Necessary	270.80 FL	*- FL
14	2		*FRONT FENDER ARCD GARNISH	Not Necessary	327.00 FL	*- FL
15	2		*HEADLAMP (LED)	Cracked	3,916.80 FL	*3,916.80 FL
16	2		*HEADLAMP LOWER BRACKET	Cracked	70.40 FL	*70.40 FL
17	2		*HEADLAMP SIDE BRACKET	Cracked	82.00 FL	*82.00 FL
18	1		*GRILLE CENTRE SUPPORT BRACKET	Cracked	49.00 FL	*49.00 FL
19	1		*GRILLE LOGO	Necessary	28.00 FL	*28.00 FL
20	1		*GRILLE LOGO GARNISH	Cracked	485.00 FL	*485.00 FL
21	1		*CENTRE GRILLE	Cracked	370.00 FL	*370.00 FL
22	1		*BONNET	Dented	1,126.00 FL	*1,126.00 FL
23	1		*BONNET LOCK	Damaged	178.00 FL	*178.00 FL
24	2		*BONNET INNER RUBBER (FRONT)	Not Necessary	54.00 FL	*- FL
25	2		*BONNET INNER RUBBER (SIDE)	Not Necessary	58.00 FL	*- FL
26	1		*BONNET INSULATOR	Not Necessary	122.40 FL	*- FL
27	2		*BONNET STOPPER	Not Necessary	39.00 FL	*- FL
28	2		*BONNET HINGE	Bent	97.00 FL	*97.00 FL
29	1		*FRONT SUPPORT PANEL	Buckled	796.00 FL	*796.00 FL
30	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	185.00 FL	*185.00 FL
31	1		*RADIATOR	Cracked	1,291.70 FL	*1,291.70 FL
32	2		*RADIATOR TOP BRACKET	Necessary	77.20 FL	*77.20 FL
33	1		*RADIATOR TOP HOSE	Not Necessary	89.60 FL	*- FL
34	1		*RADIATOR LOWER HOSE	Not Necessary	96.20 FL	*- FL
35	1		*RADIATOR FAN MOTOR	Not Necessary	389.00 FL	*- FL
36	1		*RADIATOR FAN BLADE	Not Necessary	135.60 FL	*- FL
37	1		*RADIATOR FAN COWLING	Not Necessary	105.00 FL	*- FL
38	1		*RADIATOR CAP	Not Necessary	34.20 FL	*- FL
39	1		*RADIATOR CAP HOSE	Not Necessary	45.80 FL	*- FL
40	2		*RADIATOR SIDE GARNISH	Not Necessary	136.00 FL	*- FL
41	4		*RADIATOR RUBBER MOUNTING	Necessary	112.00 FL	*112.00 FL
42	1		*THERMOSTAT HOUSING	Not Necessary	368.90 FL	*- FL
43	1		*AIR CON CONDENSER	Dented	898.00 FL	*898.00 FL
44	4		*AIR CON CONDENSER MOUNTING RUBBER	Necessary	112.00 FL	*112.00 FL
45	1		*AIR CON FAN MOTOR	Not Necessary	358.00 FL	*- FL
46	1		*AIR CON FAN BLADE	Not Necessary	135.60 FL	*- FL
47	1		*AIR CON FAN COWLING	Not Necessary	175.00 FL	*- FL
48	1		*AIR CON PIPE (OUTLET)	Not Necessary	367.00 FL	*- FL
49	1		*AIR DUCT	Not Necessary	142.00 FL	*- FL
50	1		*AIR FLEXIBLE DUCT	Not Necessary	165.00 FL	*- FL
51	1		*AIR CLEANER RESONATOR	Not Necessary	360.00 FL	*- FL
52	1		*AIR CLEANER RESONATOR DUCT	Not Necessary	150.00 FL	*- FL
53	1		*AIR CLEANER	Not Necessary	685.30 FL	*- FL
54	1		*WATER PUMP	Not Necessary	1,385.60 FL	*- FL
55	1		*MANIFOLD	Cracked	896.30 FL	*896.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*MANIFOLD AIR HOSE	Not Necessary	168.30 FL	*- FL
57	1		*MANIFOLD AIR HOSE CLIP	Not Necessary	38.00 FL	*- FL
58	1		*WASHER TANK	Not Necessary	235.60 FL	*- FL
59	1		*WASHER TANK MOTOR	Not Necessary	139.20 FL	*- FL
60	2		*HORN	Not Necessary	210.00 FL	*- FL
61	1		*FRONT CHASSIS MEMBER RH	Not Necessary	755.20 FL	*- FL
62	1		*RESORNATOR BOX	Not Necessary	360.00 FL	*- FL
63	1		*FRONT WIRE HARNESS	Not Necessary	1,980.00 FL	*- FL
64	1		*FRONT WIRE HARNESS HOLDER	Not Necessary	68.20 FL	*- FL
65	1		*REAR BUMPER	Distorted	865.50 FL	*865.50 FL
66	2		*REAR BUMPER REFLECTOR	Cracked	356.40 FL	*356.40 FL
67	2		*REAR BUMPER SIDE	Torn	460.00 FL	*460.00 FL
68	2		*REAR BUMPER SIDE RETAINER	Not Necessary	114.00 FL	*- FL
69	2		*TAIL LAMP	Cut	1,007.80 FL	*1,007.80 FL
70	2		*TAIL LAMP INNER PANEL (LOWER)	Not Necessary	958.00 FL	*- FL
71	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
72	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
73	1		*TAILGATE EMBLEM VEZEL	Necessary	75.50 FL	*75.50 FL
74	1		*TAILGATE EMBLEM HYBRID	Necessary	86.50 FL	*86.50 FL
75	1		*TAILGATE OUTER GARNISH	Cracked	267.80 FL	*267.80 FL
76	1		*TAILGATE REVERSE CAMERA	Not Necessary	1,352.00 FL	*- FL
77	2		*TAILGATE SIDE LAMP	Cut	574.80 FL	*574.80 FL
78	2		*TAILGATE DAMPER	Not Necessary	361.40 FL	*- FL
79	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
80	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
81	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
82	1		*TAILGATE TOP LOCK	Damaged	180.00 FL	*180.00 FL
83	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
84	1		*TAILGATE INNER TRIM	Cracked	263.40 FL	*263.40 FL
85	1		*TAILGATE WEATHERSTRIP	Torn	168.40 FL	*168.40 FL
86	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
87	1		*TAILGATE LOCK DECTECTOR	Not Necessary	379.00 FL	*- FL
88	1		*BUZZER	Cracked	109.00 FL	*109.00 FL
89	2		*REAR FENDER INNER TRIM	Cracked	798.20 FL	*798.20 FL
90	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
91	2		*REAR FENDER ARCED GARNISH	Cracked	369.40 FL	*369.40 FL
92	2		*REAR WHEEL HOUSE PANEL	Not Necessary	1,792.60 FL	*- FL
93	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
94	1		*REAR END PANEL TOP GARNISH	Deformed	146.30 FL	*146.30 FL
95	1		*REAR FLOOR PANEL	Distorted	1,130.00 FL	*1,130.00 FL
96	1		*REAR FLOOR TOWING PANEL	Repair	545.00 FL	*- FL
97	1		*REAR FLOOR BOTTOM CROSS MEMBER	Repair	250.80 FL	*- FL
98	2		*REAR FLOOR SIDE PANEL	Not Necessary	595.20 FL	*- FL
99	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	269.00 FL	*269.00 FL
100	1		*REAR FLOOR PANEL TOP BOARD	Deformed	325.70 FL	*325.70 FL
101	1		*REAR STORAGE BOX	Deformed	495.00 FL	*495.00 FL
102	1		*HYBRID CHARGER	Not Necessary	1,687.00 FL	*- FL
103	1		*HYBRID FAN ASSY COOLING	Not Necessary	590.20 FL	*- FL
104	1		*HYBRID DUCT ASSY AIR INTAKE	Not Necessary	240.20 FL	*- FL
105	1		*HYBRID DUCT ASSY IPU INTAKE	Not Necessary	255.40 FL	*- FL
106	1		*HYBRID CASE COMP IPU	Not Necessary	285.40 FL	*- FL
107	1		*HYBRID COVER COMP IPU	Not Necessary	355.20 FL	*- FL
108	1		*HYBRID COVER COMP REAR	Not Necessary	170.30 FL	*- FL
109	1		*HYBRID BATTERY	Not Necessary	8,500.20 FL	*- FL
110	1		*HYBRID BATTERY WIRE HARNESS	Not Necessary	385.20 FL	*- FL
111	1		*REAR CHASSIS MEMBER	Not Necessary	797.40 FL	*- FL
112	1		*SET CENTER EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
113	1		*CENTER EXHAUST	Not Necessary	1,980.00 FL	*- FL
114	1		*CENTER EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
115	1		*REAR EXHAUST INSULATOR	Not Necessary	155.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*REAR EXHAUST PIPE	Repair	980.00 FL	*- FL
117	4		*REAR EXHAUST MOUNTING	Not Necessary	117.60 FL	*- FL
118	1		*SET REAR EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
119	1		*FRONT NUMBER PLATE	Cut	50.00 FS	*50.00 FS
120	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
121	1		*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
122	1		*SET ENGINE UNDER CENTER COVER CLIP	Not Necessary	50.00 FS	*- FS
123	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
124	1		*SET GRILLE LOGO GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
125	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
126	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
127	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
128	1		*COOLANT	Necessary	80.00 FS	*40.00 FS
129	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
130	1		*REAR BUMPER TOP COVER (SPECAIL TYPE)	Cracked	350.00 FS	*200.00 FS
131	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
132	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
133	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
134	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
135	1		*TAILGATE SIDE LINING (SPECAIL TYPE)	Necessary	180.00 FS	*80.00 FS
136	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
137	2		*TAIL LAMP INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
138	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*60.00 FS
139	2		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
140	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
141	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
142	1		*REAR FLOOR PANEL SEALANT	Necessary	350.00 FS	*200.00 FS
143	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
144	1		*REAR EXHAUST CHROME PIPE (SPECAIL TYPE)	Not Necessary	480.00 FS	*- FS
145	1		*TRIANGLE BREAKDOWN SIGN	Not Necessary	180.00 FS	*- FS
146	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	62,142.55	23,497.10
- List Item Discount on L Items 20.00/20.00% (\$)	11,786.51	4,467.42
Total Parts (\$)	50,356.04	19,029.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS (FRONT)	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,600.00	1,000.00
3	REMOVE AND REFIX WIREHARNES AND WIRING CHECKING (FRONT)	New	180.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS (FRONT)	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)	New	80.00	60.00
6	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	0.00
7	REMOVE AND REFIX WATER PUMP (FRONT)	New	280.00	0.00
8	REMOVE AND REFIX MANIFOLD (FRONT)	New	280.00	120.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC (FRONT)	New	180.00	0.00
10	PANEL BEATING REMOVAL AND REPLACING PARTS (REAR)	New	2,200.00	1,200.00
11	TO SPRAY PAINT AFFECTED AREA (REAR)	New	2,000.00	800.00
12	TUFF COAT (REAR)	New	250.00	100.00
13	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR (REAR)	New	250.00	120.00
14	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING (REAR)	New	80.00	50.00
15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	80.00	50.00
16	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
17	REMOVE AND REFIX TAILGATE WINDSCREEN (REAR)	New	120.00	120.00
18	TRANSFER TAILGATE MECHANISM (REAR)	New	80.00	60.00
19	CONDUCT WATER LEAKAGE TEST (REAR)	New	100.00	0.00
20	TO REMOVE AND REFIX AND REPROGRAM HYBRIC SYSTEM (REAR)	New	1,200.00	450.00
21	REMOVE AND REFIX REAR EXHAUST PIPE (REAR)	New	180.00	60.00
22	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT (REAR)	New	80.00	0.00
Gross Labour Cost (\$\$)			11,450.00	5,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >