

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100096/UMA3Q2**Date:** 09/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240097096
Claimant Vehicle No : SML6261G **Insured Vehicle No :** SMF590C
 Date of Loss: 03/10/2024 Nature of Claim: TP Claim No: 0469182557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML6261G**
 Make & Model: MAZDA MX-5, 2.0 RHT (NC3) (A) Engine No: LF10882156
 Reg. Date: 18/12/2009 (Man. Year: 2009) Chassis No: JM0NC30F2A0201566
 Colour: Red Odometer: 169613 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,929.90	7,997.12	9,932.78	55.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	2,010.00	1,190.00	37.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,129.90	10,007.12	11,122.78	52.64
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	21,129.90	8,000.00	13,129.90	62.14
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,727.25		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment: 04/10/2024
 Date Inspected: 04/10/2024 Inspected At: Super-zee Motor Service (HQ)
 BLK 14 DEFU LANE 10, #01-402
 Singapore 539195
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,721.90 F	*1,558.00 FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	124.80 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
4	1		*FRONT FENDER RH	Dented / Bent	587.20 F	*587.20 FL
5	1		*FRONT DOOR RH	Repair	1,310.10 F	*- FL
6	1		*FRONT DOOR OUTER HANDLE RH	Cut	285.50 F	*285.50 FL
7	1		*FRONT DOOR SIDE MIRROR RH	Cracked	526.60 F	*526.60 FL
8	1		*REAR FENDER RH	Repair	1,005.20 F	*- FL
9	1		*FRONT CROSS MEMBER	Bent / Twisted	2,165.80 F	*2,164.00 FL
10	1		*FRONT LOWER ARM RH	Bent / Twisted	614.30 F	*614.30 FL
11	1		*FRONT LOWER ARM LH	Bent / Twisted	753.10 F	*614.30 FL
12	1		*FRONT KNUCKLE ARM LH	Bent	651.20 F	*534.00 FL
13	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	898.60 F	*650.00 FL
14	1		*FRONT TIE ROD LH	Serviceable	269.30 F	*- FL
15	1		*FRONT RACK END LH	Not Necessary	377.60 F	*- FL
16	1		*REAR KNUCKLE ARM LH	Not Necessary	1,610.20 F	*- FL
17	1		*REAR KNUCKLE ARM BEARING LH	Not Necessary	413.50 F	*- FL
18	2		*FRONT TYRE RIMS RH/LH	Cut / Bent	1,900.00 FS	*1,200.00 FS
19	1		*FRONT TYRE RH/LH (LOCAL PURCHASE) (\$280.00) (50%)	N/S Cut	750.00 FS	*140.00 FS
20	2		*REAR TYRE RIM RH/LH	Cut (2 PCS ONLY)	1,900.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,929.90	9,503.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,506.78
Total Parts (\$\$)	17,929.90	7,997.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	100.00	100.00
2	TO DISMANTLE & REPLACE DAMAGED BODY PARTS AND PANELBEARING	New	950.00	580.00
3	TO DISMANTLE & REPLACE UNDERCARRIAGE PARTS	New	550.00	300.00
4	TO PUTTY ,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	1,200.00	880.00
5	TO APPLY RUSTPOOFING ON REPAIRED ,REPLACED PANEL	New	200.00	30.00
6	TO CHECK ELECTRICAL WIRING FUNCTIONS	New	80.00	20.00
7	COMPUTERISED WHEEL ALIGNMENT	New	120.00	100.00
Gross Labour Cost (\$\$)			3,200.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >