

# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

## REPAIR ESTIMATE GBJ9042T

Not Authorised  
C/Ping &  
Recovery After Pain  
9-5 days

| No. | Qty   | Nett Items                           | Ref/Qty  | Price       | Remarks |
|-----|-------|--------------------------------------|----------|-------------|---------|
| 1   | 1     | Rear bumper                          | \$       | 595.20      | ✓       |
| 2   | 2     | Rear bumper side retainer            | \$       | 140.80      | X       |
| 3   | 2     | Rear bumper reflector                | \$       | 191.60      | X       |
| 4   | 1 set | Rear bumper clips                    | \$       | 50.00       | ✓       |
| 5   | 1     | Rear bumper inner foam               | \$       | 124.70      | ?       |
| 6   | 1     | Rear LH tailgate                     | Ref/Qty  | 1,967.80    | ✓       |
| 7   | 1     | Rear LH tailgate outer handle        | \$       | 351.50      | ?       |
| 8   | 1     | Rear LH tailgate "NISSAN" LOGO       | \$       | 52.50       | ✓       |
| 9   | 1     | Rear LH tailgate "NV 200" emblem     | \$       | 86.40       | ✓       |
| 10  | 1     | Rear LH tailgate lower lock          | \$       | 166.10      | X       |
| 11  | 1     | Rear LH tailgate top lock            | \$       | 186.10      | X       |
| 12  | 1     | Rear RH tailgate                     | \$       | 1,753.70    | X       |
| 13  | 1     | Rear RH tailgate rubber              | \$       | 351.50      | X       |
| 14  | 1     | Rear RH tailgate lower lock          | \$       | 166.10      | X       |
| 15  | 1     | Rear RH tailgate top lock            | \$       | 186.10      | X       |
| 16  | 1 set | Rear tailgate inner trim board clips | \$       | 80.00       | X       |
| 17  | 1     | Rear tailgate weatherstrip           | \$       | 79.10       | X       |
| 18  | 1     | Rear end panel                       | \$       | 385.00      | ?       |
|     |       |                                      | \$       | 6,914.20    |         |
|     |       |                                      | Less 10% | \$ 691.42   |         |
|     |       |                                      | Total    | \$ 6,222.78 |         |

|    |       | Special Nett Items                | Ref/Qty | Price     | Remarks |
|----|-------|-----------------------------------|---------|-----------|---------|
| 19 | 1     | Rear LH tailgate "70km/h" sticker | \$      | 15.00     | ✓       |
| 20 | 1     | Rear RH tailgate "6pax" sticker   | \$      | 15.00     | ✓       |
| 21 | 1     | Rear number plate                 | \$      | 50.00     | X       |
| 22 | 1 set | Reverse sensors                   | \$      | 280.00    | 200sm   |
| 23 | 1 set | Rear end panel sealant            | \$      | 60.00     | ?       |
| 24 | 2 set | Rear windscreen sealant           | \$      | 100.00    | 40sm    |
|    |       |                                   | Total : | \$ 520.00 |         |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

|   |  | Labour                                                                                      | Price       | Remarks     |
|---|--|---------------------------------------------------------------------------------------------|-------------|-------------|
| 1 |  | Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages. | \$ 1,000.00 | 500d        |
| 2 |  | To putty and spray Spray Paintings charges.                                                 | \$ 1,200.00 | 400d        |
| 3 |  | To remove, refit both rear tailgate windscreen glass.                                       | \$ 240.00   | 80d         |
| 4 |  | To check wirings and lightings.                                                             | \$ 40.00    | 15d         |
| 5 |  | To remove, transfer both tailgate fittings.                                                 | \$ 120.00   | 60d         |
| 6 |  | To replace reverse sensors.                                                                 | \$ 80.00    | 50d         |
| 7 |  | To apply anti rust treatment                                                                | \$ 100.00   | 30d         |
|   |  |                                                                                             | Total :     | \$ 2,780.00 |

Total Parts and Labour : \$ 9,522.78