



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100102/Unp3
16 RAFFLES QUAY	Date:	14/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9922M	Veh. Inspected	SMT 2963Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008667MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	03/10/2024

2. Vehicle Details

Make & Model	MAZDA 3 (A)	C.C	1496
Engine No.	P520330328	Year of Reg.	24/11/2015
Chassis No.	JM6BM42A8G0324493	Colour	SILVER
Odometer	116071 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	YOKOHAMA	6
L/H Front Tyre	205/60R16	YOKOHAMA	6
R/H Rear Tyre	205/60R16	YOKOHAMA	6
L/H Rear Tyre	205/60R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/10/2024	Inspection Date	04/10/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days