

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060020/APA3Q2**Date:** 12/11/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070960
Claimant Vehicle No : SLT6050T **Insured Vehicle No :** SLT3625E
 Date of Loss: 05/06/2024 Nature of Claim: TP Claim No: 4516120089SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT6050T**
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4428028
 Reg. Date: 02/11/2017 (Man. Year: 2017) Chassis No: RU11228026
 Colour: Blue Odometer: 103767 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,504.68	24,062.96	24,441.72	50.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,700.00	5,390.00	8,310.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,204.68	29,452.96	32,751.72	52.65
Approved Total (Overridden) (S\$)		23,550.00		
(S\$)	62,204.68	23,550.00	38,654.68	62.14
+ GST 9.00/9.00% (S\$)	5,598.42	2,119.50	3,478.92	62.14
Nett Amount (S\$)	67,803.10	25,669.50	42,133.60	62.14
+ Loss of Use (21.0 x S\$60.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		58.25		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		27,047.75		
Global Sum Settlement (S\$)		27,000.00		

INSPECTION

Date of Assignment: 06/06/2024
 Date Inspected: 06/06/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	927.50 FL	*745.00 FL
2	1		*FRONT BUMPER TOWING COVER	Missing	27.40 FL	*27.40 FL
3	1		*FRONT BUMPER LOWER LIP	Deformed	351.00 FL	*351.00 FL
4	2		*FRONT BUMPER FOGLAMP	Cracked	655.40 FL	*655.40 FL
5	1		*FRONT BUMPER FOGLAMP COVER	O/S Missing	98.00 FL	*49.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	189.00 FL	*189.00 FL
7	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	46.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	356.00 FL	*356.00 FL
9	1		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Not Necessary	86.55 FL	*- FL
10	2		*ENGINE SIDE COVER GARNISH	Not Necessary	130.80 FL	*- FL
11	1		*ENGINE UNDER COVER	Torn	589.10 FL	*268.00 FL
12	2		*FRONT FENDER	Repair	1,160.00 FL	*- FL
13	2		*FRONT FENDER INNER COWLING	Not Necessary	270.80 FL	*- FL
14	2		*FRONT FENDER ARCD GARNISH	Not Necessary	327.00 FL	*- FL
15	1		*FRONT WIPER PANEL GARNISH	Not Necessary	260.00 FL	*- FL
16	2		*HEADLAMP (LED)	Cracked	3,916.80 FL	*3,916.80 FL
17	2		*HEADLAMP LOWER BRACKET	Cracked	70.40 FL	*70.40 FL
18	2		*HEADLAMP SIDE BRACKET	Cracked	82.00 FL	*82.00 FL
19	1		*GRILLE CENTRE SUPPORT BRACKET	Cracked	49.00 FL	*49.00 FL
20	1		*GRILLE LOGO GARNISH	Cracked	485.00 FL	*485.00 FL
21	1		*CENTRE GRILLE BASE	Cracked	370.00 FL	*370.00 FL
22	2		*CENTRE GRILLE CHROME	Cracked	178.00 FL	*178.00 FL
23	1		*BONNET	Distorted	1,126.00 FL	*1,126.00 FL
24	1		*BONNET LOCK	Damaged	178.00 FL	*178.00 FL
25	2		*BONNET INNER RUBBER (FRONT)	Not Necessary	54.00 FL	*- FL
26	2		*BONNET INNER RUBBER (SIDE)	Not Necessary	58.00 FL	*- FL
27	1		*BONNET INSULATOR	Crumpled	122.40 FL	*122.40 FL
28	4		*BONNET STOPPER	Not Necessary	78.00 FL	*- FL
29	2		*BONNET HINGE	Not Necessary	97.00 FL	*- FL
30	1		*FRONT SUPPORT PANEL	Buckled	796.00 FL	*796.00 FL
31	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	185.00 FL	*185.00 FL
32	1		*RADIATOR	Bent	1,291.70 FL	*1,291.70 FL
33	1		*RADIATOR SPARE TANK	Not Necessary	86.40 FL	*- FL
34	2		*RADIATOR TOP BRACKET	Damaged	77.20 FL	*77.20 FL
35	1		*RADIATOR TOP HOSE	Not Necessary	89.60 FL	*- FL
36	1		*RADIATOR LOWER HOSE	Not Necessary	96.20 FL	*- FL
37	1		*RADIATOR FAN MOTOR	Not Necessary	389.00 FL	*- FL
38	1		*RADIATOR FAN BLADE	Not Necessary	135.60 FL	*- FL
39	1		*RADIATOR FAN COWLING	Cracked	105.00 FL	*105.00 FL
40	1		*RADIATOR CAP	Not Necessary	34.20 FL	*- FL
41	1		*RADIATOR CAP HOSE	Not Necessary	45.80 FL	*- FL
42	2		*RADIATOR SIDE GARNISH	Deformed	136.00 FL	*136.00 FL
43	4		*RADIATOR RUBBER MOUNTING	Not Necessary	112.00 FL	*- FL
44	1		*THERMOSTAT HOUSING	Not Necessary	368.90 FL	*- FL
45	1		*AIRCON CONDENSER	Bent	898.00 FL	*898.00 FL
46	4		*AIRCON CONDENSER MOUNTING RUBBER	Not Necessary	112.00 FL	*- FL
47	1		*AIRCON FAN MOTOR	Damaged	358.00 FL	*358.00 FL
48	1		*AIRCON FAN BLADE	Not Necessary	135.60 FL	*- FL
49	1		*AIRCON FAN COWLING	Cracked	175.00 FL	*175.00 FL
50	1		*AIR CON PIPE (OUTLET)	Not Necessary	367.00 FL	*- FL
51	1		*AIR DUCT	Deformed	142.00 FL	*142.00 FL
52	1		*AIR FLEXIBLE DUCT	Not Necessary	165.00 FL	*- FL
53	1		*AIR CLEANER RESONATOR	Not Necessary	360.00 FL	*- FL
54	1		*AIR CLEANER RESONATOR DUCT	Not Necessary	150.00 FL	*- FL
55	1		*AIR CLEANER	Cracked	685.30 FL	*685.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*ALTERNATOR	Cracked	1,562.90 FL	*1,562.90 FL
57	1		*MANIFOLD	Cut	896.30 FL	*896.30 FL
58	1		*MANIFOLD AIR HOSE	Not Necessary	168.30 FL	*- FL
59	1		*MANIFOLD AIR HOSE CLIP	Not Necessary	38.00 FL	*- FL
60	1		*WATER COOLER	Not Necessary	655.00 FL	*- FL
61	2		*WATER COOLER HOSE	Not Necessary	170.00 FL	*- FL
62	2		*HORN	Not Necessary	210.00 FL	*- FL
63	1		*FRONT CHASSIS MEMBER	Repair	755.20 FL	*- FL
64	1		*BATTERY TRAY	Not Necessary	38.00 FL	*- FL
65	1		*BATTERY BASE PANEL	Not Necessary	87.00 FL	*- FL
66	1		*ECU	Not Necessary	2,884.70 FL	*- FL
67	1		*ECU BRACKET	Not Necessary	255.30 FL	*- FL
68	1		*SET ENFINE MOUNTING	Not Necessary	760.00 FL	*- FL
69	1		*GEAR BOX MOUNTING	Not Necessary	483.00 FL	*- FL
70	1		*WASHER TANK	Not Necessary	165.00 FL	*- FL
71	1		*WASHER TANK MOTOR	Not Necessary	103.00 FL	*- FL
72	1		*FRONT WIRE HARNESS	Not Necessary	1,980.00 FL	*- FL
73	1		*FRONT WIRE HARNESS HOLDER	Not Necessary	68.20 FL	*- FL
74	1		*REAR BUMPER	Distorted	865.50 FL	*865.50 FL
75	1		*REAR BUMPER REFLECTOR	O/S Cracked	356.40 FL	*178.20 FL
76	2		*REAR BUMPER SIDE	Cracked	460.00 FL	*460.00 FL
77	2		*REAR BUMPER SIDE RETAINER	Not Necessary	114.00 FL	*- FL
78	2		*TAIL LAMP	Cut	1,007.80 FL	*950.00 FL
79	2		*TAIL LAMP PANEL	Repair	536.00 FL	*- FL
80	2		*TAIL LAMP INNER PANEL	Repair	958.00 FL	*- FL
81	2		*TAIL LAMP INNER PANEL (UPPER)	Repair	740.00 FL	*- FL
82	2		*TAIL LAMP INNER PANEL (LOWER)	Repair	958.00 FL	*- FL
83	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
84	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
85	1		*TAILGATE EMBLEM VEZEL	Necessary	75.50 FL	*75.50 FL
86	1		*TAILGATE OUTER GARNISH	Cracked	267.80 FL	*267.80 FL
87	2		*TAILGATE SIDE LAMP	Cut	574.80 FL	*574.80 FL
88	2		*TAILGATE DAMPER	Not Necessary	361.40 FL	*- FL
89	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
90	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
91	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
92	1		*TAILGATE TOP LOCK	Damaged	180.00 FL	*180.00 FL
93	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
94	1		*TAILGATE INNER TRIM	Cracked	263.40 FL	*263.40 FL
95	2		*TAILGATE INNER SIDE TRIM	Not Necessary	96.40 FL	*- FL
96	1		*TAILGATE WEATHERSTRIP	Cut	168.40 FL	*168.40 FL
97	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
98	1		*TAILGATE HINGE	Not Necessary	95.00 FL	*- FL
99	1		*TAILGATE LOCK DETECTOR	Not Necessary	379.00 FL	*- FL
100	1		*TAILGATE LOCK DETECTOR WIRE HARNESS	Not Necessary	358.00 FL	*- FL
101	1		*BUZZER	Cracked	109.00 FL	*109.00 FL
102	1		*BUZZER WIRE HARNESS	Not Necessary	288.50 FL	*- FL
103	1		*REAR FENDER	O/S Buckled	2,240.00 FL	*1,120.00 FL
104	2		*REAR FENDER INNER TRIM	Cracked	798.20 FL	*798.20 FL
105	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
106	1		*REAR FENDER ARCED GARNISH	O/S Deformed	369.40 FL	*184.70 FL
107	1		*REAR WHEEL HOUSE PANEL RH	Repair	896.30 FL	*- FL
108	1		*REAR END PANEL	Distorted	530.00 FL	*530.00 FL
109	1		*REAR END PANEL TOP GARNISH	Cracked	146.30 FL	*146.30 FL
110	1		*REAR FLOOR PANEL	Buckled	1,130.00 FL	*1,130.00 FL
111	1		*REAR FLOOR TOWING PANEL	Bent	545.00 FL	*545.00 FL
112	1		*REAR FLOOR BOTTOM CROSS MEMBER	Repair	250.80 FL	*- FL
113	2		*REAR FLOOR SIDE PANEL	Repair	595.20 FL	*- FL
114	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	269.00 FL	*269.00 FL
115	1		*REAR FLOOR PANEL TOP BOARD	Deformed	325.70 FL	*325.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*REAR STORAGE SPONGE	Cracked	156.40 FL	*156.40 FL
117	1		*REAR CHASSIS MEMBER	Repair	797.40 FL	*- FL
118	1		*SET CENTER EXHAUST GASKET	Not Necessary	80.00 FL	*- FL
119	1		*CENTER EXHAUST	Repair	1,980.00 FL	*- FL
120	1		*CENTER EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
121	1		*REAR EXHAUST INSULATOR	Crumpled	155.00 FL	*155.00 FL
122	1		*REAR EXHAUST PIPE	Bent	980.00 FL	*780.00 FL
123	4		*REAR EXHAUST MOUNTING	Not Necessary	117.60 FL	*- FL
124	1		*SET REAR EXHAUST GASKET	Necessary	80.00 FL	*40.00 FL
125	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
126	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
127	1		*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
128	1		*FRONT BUMPER SPOILER (SPECAIL TYPE)	Smashed	1,300.00 FS	*650.00 FS
129	1		*SET ENGINE UNDER CENTER COVER CLIP	Necessary	50.00 FS	*30.00 FS
130	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
131	1		*SET GRILLE LOGO GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
132	1		*GRILLE LOGO (SPECAIL TYPE)	Necessary	80.00 FS	*40.00 FS
133	1		*SET BONNET INSULATOR CLIP	Necessary	50.00 FS	*30.00 FS
134	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
135	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
136	1		*COOLANT	Necessary	80.00 FS	*40.00 FS
137	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
138	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
139	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
140	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
141	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
142	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
143	2		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
144	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*60.00 FS
145	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	120.00 FS	*60.00 FS
146	2		*SET REAR FENDER COWLING CLIP	Not Necessary	120.00 FS	*- FS
147	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
148	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
149	1		*REAR FLOOR PANEL SEALANT	Necessary	350.00 FS	*60.00 FS
150	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
151	1		*TRIANGLE BREAKDOWN SIGN	Not Necessary	180.00 FS	*- FS
152	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
153	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
154	1		*REAR EXHAUST CHROME PIPE (SPECAIL TYPE)	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	59,440.85	29,688.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	10,936.17	5,625.74
Total Parts (\$\$)	48,504.68	24,062.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS (FRONT)	New	2,000.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	New	1,800.00	800.00
3	REMOVE AND REFIX WIREHARNES AND WIRING CHECKING	New	180.00	30.00
4	REMOVE AND REFIX AND REPROGRAMMING ECU	New	800.00	0.00
5	REMOVE AND REFIX MANIFOLD ALTERNATOR THROTTLE BODY	New	300.00	200.00
6	LIGHT UP ENGINE	New	550.00	0.00
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
9	REFOCUS HEADLAMP BEAM	New	60.00	0.00
10	REMOVE AND REFIX ALTERNATOR	New	280.00	0.00
11	REMOVE AND REFIX MANIFOLD	New	280.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
13	PANEL BEATING ,REMOVAL AND REPLACING PARTS (REAR)	New	2,600.00	1,600.00
14	TO SPRAY PAINT AFFECTED AREA (REAR)	New	2,200.00	1,200.00
15	TUFF COAT	New	250.00	150.00
16	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	150.00
17	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
18	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
19	REAR CHASSIS ALIGNMENT	New	250.00	0.00
20	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
21	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
22	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
23	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
24	REMOVE AND REFIX REAR EDLC	New	150.00	0.00
25	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	60.00
26	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			13,700.00	5,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >