



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100109/Uvp3e2
16 RAFFLES QUAY	Date:	06/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8503X	Veh. Inspected	SMC 8389G
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008565MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	04/10/2024

2. Vehicle Details

Make & Model	HONDA ODYSSEY (A)	C.C	2354
Engine No.	K24Z21301489	Year of Reg.	16/10/2009
Chassis No.	JHMRB38509C201482	Colour	BLUE
Odometer	272628 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	MICHELIN	6
L/H Front Tyre	215/55R17	MICHELIN	6
R/H Rear Tyre	215/55R17	MICHELIN	6
L/H Rear Tyre	215/55R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2024	Inspection Date	04/10/2024
Survey held at	JOO HAK KEE AUTO PTE LTD - 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 25 Working Days