



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SCN 113Z

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$15.00	\$15.00
1	RIGHT REAR LAMP COMBINATION (SN)	CRACKED	\$840.76	\$840.76
1	REAR BUMPER (SN)	DEFORMED	\$1,705.44	\$1,705.44
1	LHR CHROME MOULDING (SN)	NECESSARY	\$207.42	\$207.42
1	RHR CHROME MOULDING (SN)	NECESSARY	\$207.42	\$207.42
1	BRACKET (SN)	NECESSARY	\$57.90	\$57.90
12	CUPPED BLIND RIVET (SN)	NECESSARY	\$66.00	\$66.00
1	LOWER RHR BRACKET (SN)	CRACKED	\$70.12	\$70.12
1	RHR EXHAUST TIP CHROME TRIM STRIP (SN)	SERVICEABLE	\$225.86	\$0.00
1	RHR SIDE STABILITY (SN)	CRACKED	\$118.84	\$118.84
1	RHR BASIC MOUNTING FOR BUMPER (SN)	CRACKED	\$92.10	\$92.10
1	TOP RHR BASIC MOUNTING FOR BUMPER (SN)	CRACKED	\$50.51	\$50.51
2	DISTANCE SENSOR (SN)	SERVICEABLE	\$402.34	\$0.00
6	SPACER RING (SN)	NECESSARY	\$53.34	\$53.34
2	CUPPED BLIND RIVET (SN)	NECESSARY	\$11.00	\$11.00
1	REAR LOWER BUMPER (SN)	DEFORMED	\$441.74	\$441.74
1	REAR BUMPER CHROME MOULDING (SN)	CRACKED	\$414.53	\$414.53
1	COVER, TOWING EYE (SN)	NOT NECESSARY	\$161.87	\$0.00
1	RIGHT REFLECTING EMITTER (SN)	CRACKED	\$49.88	\$49.88
1	BASIC MOUNTING FOR BUMPER (SN) (ADDITIONAL)	CRACKED	\$94.05	\$94.05
1	RIGHT REAR SHIELDING (SN) (ADDITIONAL)	CRACKED	\$99.14	\$99.14
1	RIGHT TAIL PIPE COVER (SN) (ADDITIONAL)	CUT	\$493.48	\$493.48
1	TOP BASIC MOUNTING FOR BUMPER (SN) (ADDITIONAL)	CRACKED	\$50.51	\$50.51
			\$5,929.25	\$5,139.18
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD		\$380.00	\$380.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE		\$120.00	\$120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH		\$4,320.00	\$1,920.00
	RESPRAY ON RHR FENDER, REAR BUMPER AND ACCIDENT AFFECTED AREA		\$3,200.00	\$1,600.00
			\$8,020.00	\$4,020.00
GRAND TOTAL			\$13,949.25	\$9,159.18
	RECOMMENDED COST OF REPAIRS			\$9,159.18
Report Ref No: CS/FCI24100111/Rnp3e2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.