



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YR 1358X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP RH (N)	BROKEN	470.70	378.00
	LESS 10% DISCOUNT		-47.07	-37.80
			423.63	340.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE LAMP (SN)	NOT NECESSARY	50.00	-
1	REAR NO. PLATE BASE (SN)	BROKEN	80.00	45.00
1	REAR NO. PLATE (SN)	BENT	45.00	30.00
1	REFLECTIVE TAPE YELLOW & BLACK (SN)	CUT	80.00	60.00
1	REAR REINFORCEMENT BAR (SN)	TO REPAIR SEE LABOUR	300.00	-
			555.00	135.00
	<u>LABOUR</u>			
	TO PANEL BEAT & WELDING, ALIGN REAR PORTION, TO REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT BAR.		700.00	200.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.		100.00	20.00
	TO CHECK AND RECTIFY LIGHTING & WIRING.		100.00	30.00
	TO SPRAY PAINTING REAR PORTIONS & OTHER AFFECTED AREAS.		600.00	200.00
			1,500.00	450.00
	GRAND TOTAL		2,478.63	925.20
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			925.20

Report Ref No. CS/FCI24100112/Evp3e2(N)

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.