

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24100116/ANH3E2
Date: 13/01/2025REFERENCE

Insured/Claimant:	TAN SANG THAI (CHEN SHUANGTAI)	Policy No:	7230128591
Date of Loss:	05/10/2024	Nature of Claim:	OD Claim No: 6516670045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY338B		
Make & Model:	AUDI Q5, 2.0 TFSI QU (180 BHP) (A)	Engine No:	DMS121062
Reg. Date:	27/12/2023 (Man. Year: 2022)	Chassis No:	WAUZZZF4P2043959
Colour:	White	Odometer:	23479 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$265,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,077.00	20,010.08	30,066.92	60.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,322.00	11,322.00	4,000.00	26.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	65,399.00	31,332.08	34,066.92	52.09
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	64,899.00	30,832.08	34,066.92	52.49
+ GST 9.00/9.00% (S\$)	5,840.91	2,774.89	3,066.02	52.49
Nett Amount (S\$)	70,739.91	33,606.97	37,132.94	52.49

INSPECTION

Date of Assignment:	07/10/2024		
Date Inspected:	08/10/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,630.00 FS	*1,304.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	272.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	96.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	282.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	335.00 FS	*- FS
6	1		*FRONT BUMPER UNDERRUN BAR - CENTER	Torn	1,090.00 FS	*872.00 FS
7	2		*FRONT BUMPER SPOILER - LH / RH	Not Necessary	564.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	529.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	598.00 FS	*- FS
10	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	84.00 FS	*- FS
11	2		*FRONT PARKING AID SENSOR	Not Necessary	572.00 FS	*- FS
12	6		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	17.00 FS	*- FS
13	1		*RADIATOR GRILLE	Cracked	4,178.00 FS	*3,342.40 FS
14	1		*QUATTRO EMBLEM	Necessary	125.00 FS	*99.60 FS
15	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	303.00 FS	*242.40 FS
16	1		*360 DEGREE CAMERA	Not Necessary	1,353.00 FS	*- FS
17	1		*360 DEGREE CAMERA BRACKET	Not Necessary	109.00 FS	*- FS
18	1		*360 DEGREE CAMERA SECURING PLATE	Not Necessary	42.00 FS	*- FS
19	1		*360 DEGREE CAMERA COVER CAP	Not Necessary	158.00 FS	*- FS
20	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	98.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Cracked	162.00 FS	*129.20 FS
22	1		*CAUTION STICKER	Necessary	25.00 FS	*19.44 FS
23	1		*A/C STICKER	Necessary	25.00 FS	*19.44 FS
24	1		*OIL STANDARD STICKER	Necessary	25.00 FS	*19.44 FS
25	1		*FRONT FOAM FILLER PIECE	Cracked	223.00 FS	*178.00 FS
26	1		*FRONT REINFORCEMENT BEAM	Dented	1,195.00 FS	*956.00 FS
27	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	644.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	70.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE - CENTER	Not Necessary	70.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	70.00 FS	*- FS
31	2		*RADIATOR AIR GUIDE - LH / RH	Torn	156.00 FS	*123.84 FS
32	1		*RADIATOR LOURVE	Cracked	654.00 FS	*523.20 FS
33	1		*RADIATOR LOURVE SERVOMOTOR	Not Necessary	209.00 FS	*- FS
34	2		*LED HEADLIGHT - LH / RH	Not Necessary	16,800.00 FS	*- FS
35	2		*LIFT CYLINDER - LH / RH	Not Necessary	334.00 FS	*- FS
36	1		*LIFT CYLINDER HOSE - LH / RH	Not Necessary	159.00 FS	*- FS
37	2		*LED HEADLIGHT TOP COVER - LH / RH	Not Necessary	100.00 FS	*78.88 FS
38	1		*BONNET	Dented	4,543.00 FS	*3,634.40 FS
39	2		*BONNET HINGE - LH / RH	Bent	398.00 FS	*317.60 FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	156.00 FS	*- FS
41	2		*BONNET STRIKER - LH / RH	Not Necessary	298.00 FS	*- FS
42	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	70.00 FS	*56.24 FS
43	2		*BONNET LID LOCK SWITCH	Not Necessary	491.00 FS	*- FS
44	1		*BONNET RELEASE ELEMENT	Not Necessary	73.00 FS	*- FS
45	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,580.00 FS	*1,264.00 FS
46	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
47	1		*SUNDRIES	Necessary	600.00 FS	*17.92 FS
48	1		*FRONT LOCK CARRIER (SUPPLEMENTARY)	Cracked	1,751.00 FS	*1,400.80 FS
49	1		*READY MIX COOLANT (6PCS)(SUPPLEMENTARY)	Necessary	332.00 FS	*265.44 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BONNET IMPACT PROTECTION - CENTER (SUPPLEMENTARY)	Necessary	36.00 FS	*28.40 FS
51	2		*HEADLIGHT MOUNTING RHS/LHS (SUPPLEMENTARY)	Cracked	294.00 FS	*235.20 FS
52	2		*FRONT FENDER RHS / LHS (SUPPLEMENTARY)	Buckled	3,658.00 FS	*2,926.40 FS
53	2		*FRONT FENDER BRACE RHS / LHS (SUPPLEMENTARY)	Bent	532.00 FS	*424.80 FS
54	1		*OUTER TEMPERATURE SENSOR BRACKET (SUPPLEMENTARY)	Necessary	27.00 FS	*15.84 FS
55	2		*FRONT DOOR WINDOW SLOT SEAL RHS / LHS (SUPPLEMENTARY)	Cut	1,548.00 FS	*1,237.60 FS
56	2		*FRONT FENDER TOP LEDGE COVER OUTER RHS / LHS (SUPPLEMENTARY)	Necessary	196.00 FS	*155.52 FS
57	2		*FRONT FENDER TOP LEDGE COVER INNER RHS / LHS (SUPPLEMENTARY)	Necessary	78.00 FS	*62.08 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	50,077.00	20,010.08
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	3,700.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
6	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM (SUPPLEMENTARY)	New	1,800.00	1,800.00
7	TO CARRY OUT VACUUM AND REGAS FOR R1234 (SUPPLEMENTARY)	New	1,200.00	1,200.00
8	TO RENEW BOTH FRONT FENDER (SUPPLEMENTARY)	New	1,000.00	1,000.00
9	TO REPAIR LHS FRONT UPPER A-PILLAR (SUPPLEMENTARY)	New	250.00	250.00
10	TO RESPRAY BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS (SUPPLEMENTARY)	New	3,300.00	3,300.00
11	TO REMOVE AND REINSTALL BOTH FRONT WING MIRROR ASSY TO RESPRAY BOTH FRONT DOORS (SUPPLEMENTARY)	New	500.00	500.00
Gross Labour Cost (\$)			15,322.00	11,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >