



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100118/Knh3m4
16 RAFFLES QUAY	Date:	01/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4017B	Veh. Inspected	SNB 8082J
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008761MFCT	Excess	\$0.00
Assign From	JOANNE TAN	Assign Date	04/10/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH (A)	C.C	1797
Engine No.	2ZR0B93295	Year of Reg.	05/11/2018
Chassis No.	ZWR800330317	Colour	METALLIC SILVER
Odometer	227713 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	YOKOHAMA	8
L/H Front Tyre	195/65R15	YOKOHAMA	8
R/H Rear Tyre	195/65R15	YOKOHAMA	8
L/H Rear Tyre	195/65R15	YOKOHAMA	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2024	Inspection Date	22/10/2024
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days