

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100121/UUA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100454616
Claimant Vehicle No :	SMC9906H	Insured Vehicle No :	SGF2878G
Date of Loss:	05/10/2024	Nature of Claim:	TP
		Claim No:	8860195014SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9906H		
Make & Model:	VOLVO S60, 2.0 T5 ABS D/AIRBAG 2WD (A)	Engine No:	B4204T112550733
Reg. Date:	30/07/2018 (Man. Year: 2018)	Chassis No:	YV1FS40LDJ2468728
Colour:	Grey	Odometer:	101054 km
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50Z R17	Rear Tyre Size:	215/50Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,117.16	7,547.79	17,569.37	69.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,440.00	4,410.00	75.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,967.16	8,987.79	21,979.37	70.98
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	30,967.16	7,100.00	23,867.16	77.07
+ GST 9.00/9.00% (S\$)	2,787.04	639.00	2,148.04	77.07
Nett Amount (S\$)	33,754.20	7,739.00	26,015.20	77.07
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		8,426.25		

INSPECTION

Date of Assignment:	08/10/2024	
Date Inspected:	08/10/2024	Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	2,556.10 FL	*2,450.00 FL
2	1		*BOOTLID VOLVO EMBLEM	Necessary	138.30 FL	*110.00 FL
3	1		*BOOTLID S60 EMBLEM	Necessary	78.40 FL	*70.00 FL
4	1		*BOOTLID T5 EMBLEM	Necessary	64.10 FL	*60.00 FL
5	2		*BOOTLID LAMP L/R	Not Necessary	956.60 FL	*- FL
6	2		*BOOTLID HINGE L/R	Not Necessary	412.60 FL	*- FL
7	1		*BOOTLID INNER LOCK	Serviceable	616.20 FL	*- FL
8	1		*BOOTLID LOCK STRIKER	Not Necessary	78.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Necessary	616.20 FL	*- FL
10	1		*REAR CAMERA	Not Necessary	1,562.30 FL	*- FL
11	1		*TAIL LAMP L/R	N/S Not Necessary /O/S Cracked	2,322.40 FL	*825.00 FL
12	1		*TAIL LAMP BRACKET L/R	N/S Not Necessary /O/S Cracked	278.60 FL	*105.00 FL
13	2		*TAIL LAMP INNER PANEL L/R	Not Necessary	386.40 FL	*- FL
14	1		*REAR BUMPER	Distorted	1,984.20 FL	*1,845.00 FL
15	1		*REAR BUMPER LOWER	Distorted	941.10 FL	*780.00 FL
16	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	312.20 FL	*290.00 FL
17	1		*REAR BUMPER CENTRE BRACKET	Not fitted	296.00 FL	*- FL
18	1		*REAR BUMPER REVERSE SENSOR L/R	O/S Cracked	598.60 FL	*245.00 FL
19	1		*SET REAR BUMPER REVERSE SENSOR BRACKET	Necessary	156.00 FL	*156.00 FL
20	1		*REAR BUMPER TOW COVER	Torn	76.30 FL	*48.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	823.40 FL	*823.40 FL
22	1		*END PANEL	Repair	1,521.10 FL	*- FL
23	1		*END PANEL GARNISH	Not Necessary	368.70 FL	*- FL
24	1		*REAR FENDER RH	Repair	2,414.20 FL	*- FL
25	1		*REAR FENDER INNER TRIM RH	Not Necessary	517.40 FL	*- FL
26	1		*REAR FENDER LH	Not Necessary	2,414.20 FL	*- FL
27	1		*REAR FENDER INNER TRIM LH	Not Necessary	517.40 FL	*- FL
28	2		*REAR FENDER SPLASH SHIELD L/R	Not Necessary	552.40 FL	*- FL
29	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	511.60 FL	*- FL
30	1		*SPARE TYRE PANEL	Repair	1,145.60 FL	*- FL
31	1		*REAR EXHAUST RH	Repair	891.40 FL	*- FL
32	1		*REAR EXHAUST CHROME RH	Bent	311.20 FL	*311.20 FL
33	1		*REAR EXHAUST HEAT SHIELD RH	Not Necessary	298.70 FL	*- FL
34	1		*SET REAR SENSOR WIRE	Torn	234.50 FL	*234.50 FL
35	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
36	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	70.00 FS	*- FS
38	1		*END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
39	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
40	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
41	1		*REAR FENDER INNER TRIM CLIPS RH	Not Necessary	60.00 FS	*- FS
42	1		*REAR FENDER SEALANT RH	Not Necessary	80.00 FS	*- FS
43	1		*REAR FENDER INNER TRIM CLIP LH	Not Necessary	60.00 FS	*- FS
44	1		*REAR FENDER SEALANT LH	Not Necessary	80.00 FS	*- FS
45	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR WINDSCREEN SPONGE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,812.40	8,383.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,695.24	835.31
Total Parts (\$\$)	25,117.16	7,547.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REPLACE REAR REVERSE SENSOR	New	80.00	30.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	100.00	0.00
4	TO REMOVE AND TRANSFER BOOTLID FITTINGS TO NEW	New	100.00	50.00
5	TO REMOVE AND REFIT REAR INTERIOR TRIMS	New	160.00	60.00
6	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	280.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	0.00
8	TO PROVIDE LABOUR WORKMANSHIP	New	2,400.00	550.00
9	TO SPRAY PAINT ON AFFECTED PANELS	New	2,000.00	700.00
10	TO CONDUCT COMPUTERISE DIAGNOSTIC RESET	New	350.00	0.00
11	RUST PROOFING	New	150.00	30.00
Gross Labour Cost (\$\$)			5,850.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >