

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24100122/AVH3E2
Date: 20/12/2024REFERENCE**Insured/Claimant:** SYED FESHAL BIN S ABDULRAB TALIB **Policy No:** MPC23A00335301
Date of Loss: 21/09/2024 **Nature of Claim:** OD **Claim No:** DMPC2401321H/STDESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** SMF5384Z
Make & Model: TOYOTA SIENTA, 1.5 (A) **Engine No:** 2NRX397895
Reg. Date: 16/11/2018 (Man. Year: 2018) **Chassis No:** MHFZ28H3300059966
Colour: Brown **Odometer:** 53505 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size:** 195/50 R16 **Rear Tyre Size:** 195/50 R16
Front Left Side: GT 6 mm **Rear Left Side:** GT 6 mm
Front Right Side: GT 6 mm **Rear Right Side:** GT 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,958.20	3,746.00	7,212.20	65.82
Miscellaneous Items	259.00	224.00	35.00	13.51
Labour	4,550.00	1,820.00	2,730.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,767.20	5,790.00	9,977.20	63.28
+ GST 9.00/9.00% (S\$)	1,419.05	521.10	897.95	63.28
Nett Amount (S\$)	17,186.25	6,311.10	10,875.15	63.28

INSPECTION**Date of Assignment:** 07/10/2024**Date Inspected:** 07/10/2024**Inspected At:**Yew Tee Automobile Tech Pte Ltd
Blk 25 Kaki Bukit Road 4
#01-61 Synergy @ Kaki Bukit
Singapore 417800**Estimated Period of Repair:** 6.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2024)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF5384Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Deformed	480.00 F	*160.00 F
2	1		*REAR BUMPER SIDE RETAINER LH (WCP)	Damaged	80.00 F	*50.00 F
3	1		*REAR BUMPER SIDE RETAINER RH (WCP)	Damaged	80.00 F	*50.00 F
4	1		*REAR BUMPER BRACKET LH (WCP)	Not Necessary	65.00 F	*- F
5	1		*REAR BUMPER BRACKET RH (WCP)	Damaged	65.00 F	*40.00 F
6	1		*REAR BUMPER TOP GARNISH (BLACK) (WCP)	Deformed	130.00 F	*70.00 F
7	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) (WCP)	Not Necessary	170.00 F	*- F
8	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) (WCP)	Deformed	170.00 F	*40.00 F
9	1		*REAR BUMPER SIDE TOP GARNISH LH (BLACK) REFLECTOR (WCP)	Not Necessary	90.00 F	*- F
10	1		*REAR BUMPER SIDE TOP GARNISH RH (BLACK) REFLECTOR (WCP)	Cracked	90.00 F	*35.00 F
11	1		*REAR TAILGATE (WCP)	Distorted	780.00 F	*485.00 F
12	1		*REAR TAILGATE RUBBER (WCP)	Torn	230.00 F	*150.00 F
13	1		*REAR TAILGATE LOCK (WCP)	Not Necessary	320.00 F	*- F
14	1		*REAR TAILGATE LOCK CATCH (WCP)	Not Necessary	56.00 F	*- F
15	1		*REAR TAILGATE INNER BOARD (WCP)	Deformed	130.00 F	*90.00 F
16	1		*REAR TAILGATE INNER BOARD HANDLE (WCP)	Not Necessary	56.00 F	*- F
17	1		*REAR TAILGATE HINGES LH (WCP)	Bent	75.00 F	*45.00 F
18	1		*REAR TAILGATE HINGES RH (WCP)	Bent	75.00 F	*45.00 F
19	1		*REAR TAILGATE DAMPER LH (WCP)	Not Necessary	160.00 F	*- F
20	1		*REAR TAILGATE DAMPER RH (WCP)	Not Necessary	160.00 F	*- F
21	1		*REAR TAILGATE LOGO (WCP)	Not Necessary	48.00 F	*- F
22	1		*REAR TAILGATE SIENTA EMBLEM (WCP)	Not Necessary	48.00 F	*- F
23	1		*REAR TAILGATE HYBRID EMBLEM (WCP)	Not Necessary	64.00 F	*- F
24	1		*REAR TAILGATE REFLECTOR LH (WCP)	Not Necessary	440.00 F	*- F
25	1		*REAR TAILGATE REFLECTOR RH (WCP)	Cracked	440.00 F	*160.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*REAR TAILGATE OUTER CHROME (WCP)	Not Necessary	320.00 F	*- F
27	1		*REAR NUMBER PLATE LAMP LH (WCP)	Not Necessary	70.00 F	*- F
28	1		*REAR NUMBER PLATE LAMP RH (WCP)	Not Necessary	70.00 F	*- F
29	1		*REAR WINDSCREEN GLASS (WCP)	Shattered	480.00 F	*300.00 F
30	1		*REAR TAILLAMP LH (WCP)	Not Necessary	350.00 F	*- F
31	1		*REAR TAILLAMP RH (WCP)	Missing	350.00 F	*170.00 F
32	1		*REAR TAILLAMP PANEL RH (WCP)	Dented	210.00 F	*80.00 F
33	1		*REAR TAILLAMP LOWER BRACKET RH (WCP)	Cracked	60.00 F	*50.00 F
34	1		*REAR FENDER TOP RH (WCP)	Not Necessary	480.00 F	*- F
35	1		*REAR FENDER LOWER RH (WCP)	Repair	560.00 F	*- F
36	1		*REAR END PANEL (WCP)	Dented	290.00 F	*200.00 F
37	1		*REAR END PANEL INNER GARNISH (WCP)	Cracked	140.00 F	*90.00 F
<u>Supplementary #1</u>						
38	1		*REAR FENDER INNER GARNISH RH (WCP)	Deformed	250.00 F	*250.00 F
39	1		*REAR SPARE TYRE TOP BOX (WCP)	Deformed	120.00 F	*120.00 F
40	1		*RACK END PANEL (WCP)	Dented	220.00 F	*180.00 F
41	1		*REAR EXHAUST PIPE (WCP)	Dented	1,300.00 F	*600.00 FS
42	1		*REAR BOOT TRIM (WCP)	Repeated	80.00 F	*- F
43	1		*REAR END PANEL TOP BOARD (WCP)	Not Necessary	110.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$)	9,962.00	3,460.00
+ Margin on L,N Items 10.00/10.00% (\$)	996.20	286.00
Total Parts (\$)	10,958.20	3,746.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER SENSOR (SET) (DAMAGED)	200.00	200.00
2	1	REAR NUMBER PLATE (NOT NECESSARY)	35.00	0.00
3	1	REAR WINDSCREEN SEALANT (NECESSARY)	24.00	24.00
Sub Total (\$\$)			259.00	224.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO ELECTRICAL WIRING SERVICES	New	30.00	30.00
2	TO DISMANTLE & REFIT REAR SENSORS	New	60.00	50.00
3	TO DISMANTLE & REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	2,800.00	800.00
5	TO UNDERCOATING FOR RUST PROTECTION	New	60.00	40.00
6	TO SPRAY PAINTING ACCIDENT PORTION	New	1,500.00	800.00
Gross Labour Cost (\$\$)			4,550.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >